

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20001493/T1YD3E2

Date: 11/05/2020

REFERENCE

Insured/Claimant: YLS STEEL PTE LTD Policy No: Z/19/VC06/104968

Date of Loss: 15/01/2020 Nature of Claim: OD Claim No: 19/20/20/VC06/022932

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE3974J**

Make & Model: VOLVO FMX410, 10.8 D 84RT RAS DC WB5200 (M) Engine No: D11426557

Reg. Date: 28/12/2017 (Man. Year: 2017) Chassis No: YV2X1F1G0JA817075

Colour: White Odometer: 0 km

Engine Capacity: 10837 cc

Market Value/New Car Price: S\$130,000.00

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D)

Front Left Side: Continental 8 mm Rear Left Side: Continental 8/8 mm

Front Right Side: Continental 8 mm Rear Right Side: Continental 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,316.55	6,316.55	0.00	0.00
Miscellaneous Items	80.00	40.00	40.00	50.00
Labour	2,300.00	1,100.00	1,200.00	52.17
Paintwork Labour	450.00	300.00	150.00	33.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,146.55	7,756.55	1,390.00	15.20
Approved Total (Overridden) (\$\$)		6,200.00		
- Excess (\$\$)	0.00	1,500.00	-1,500.00	
(\$\$)	9,146.55	4,700.00	4,446.55	48.61
+ GST 7.00/7.00% (\$\$)	640.26	329.00	311.26	48.61
Nett Amount (\$\$)	9,786.81	5,029.00	4,757.81	48.61

INSPECTION

Date of Assignment: 28/01/2020

Date Inspected: 29/01/2020 Inspected At: 42 SUNGAI KADUT AVENUE
Repairer : Woon Meng Motor Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 May 2020)	
Parts:	N/A	VOLVO FMX410 10.8 D 84RT RAS DC WB5200 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE3974J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S (WCP)	Dented	2,100.00 F	*2,100.00 F
2	1		*ENGINE UNIT (NPA)	Not Necessary	-	*- F
Supplementary #1						
3	1		*INTER COOLER (WCP)	Leak	1,823.40 F	*1,823.40 F
4	1		*INTER COOLER UPP HOSE (WCP)	Leak	252.45 F	*252.45 F
5	1		*INTER COOLER LOWER HOSE (WCP)	Leak	224.55 F	*224.55 F
6	1		*FRONT FENDER O/S (WCP)	Scratched	165.15 F	*165.15 F
7	1		*FRONT SIDE MIRROR TOP ARM O/S (WCP)	Cracked	180.20 F	*180.20 F
8	1		*FRONT SIDE MIRROR ARM PIN O/S (WCP)	Necessary	35.30 F	*35.30 F
9	1		*RIM HUB COVER O/S. (WCP)	Scratched	90.45 F	*90.45 F
10	1		*FRONT SIDE MIRROR LOWER O/S (WCP)	Cracked	87.30 F	*87.30 F
11	1		*FRONT SIDE MIRROR ARM LOWER COVER O/S (WCP)	Cracked	17.90 F	*17.90 F
12	10		*NUT COVER (WCP)	Scratched	15.00 F	*15.00 F
13	1		*FRONT SIDE MIRROR TOP O/S (WCP)	Cracked	45.10 F	*45.10 F
14	1		*FRONT SIDE MIRROR STAY O/S (WCP)	Bent	455.85 F	*455.85 F

F=Franchise part.

Sub Total (\$\$)	5,492.65	5,492.65
+ Margin on L,N Items 15.00/15.00% (\$\$)	823.90	823.90
Total Parts (\$\$)	6,316.55	6,316.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Supplementary #1				
1	1	COOLANT (NECESSARY)	80.00	40.00
Sub Total (S\$)			80.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO PUTTY & SPRAY PAINTING	New	450.00	300.00
Labour Items				
2	TOWING FEE	New	150.00	150.00
3	TO REMOVE, REPAIR, REPLACE, INSTALL & WELD FRONT DAMAGED PARTS.	New	500.00	300.00
4	TO NUMBERING LOGO	New	300.00	150.00
Supplementary #1				
Labour Items				
5	TOWING FEE	New	150.00	0.00
6	TO R & R AIR CON SYSTEM AND REFILL & TOP UP AIR CON GAS	New	250.00	100.00
7	TO R & R INTER COOLER	New	350.00	100.00
8	TO R & R FRONT RADIATOR	New	220.00	100.00
9	TO R & R FRONT SIDE MIRROR ASSY AND CHECK FOR FUNCTION.	New	380.00	200.00
Gross Labour Cost (S\$)			2,750.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >