

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20001563/AQD3E2

Date: 14/07/2020

REFERENCE

Insured/Claimant:	TAN CHOON HENG	Policy No:	1900163619	
Date of Loss:	23/01/2020	Nature of Claim:	OD	Claim No: 8587416831SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EY6262E			
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK081954	
Reg. Date:	24/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF42KA073683	
Colour:	Grey	Odometer:	6120 km	
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$143,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,906.20	21,940.88	17,965.32	45.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,352.00	7,322.00	6,030.00	45.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,258.20	29,262.88	23,995.32	45.05
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	52,708.20	28,712.88	23,995.32	45.52
+ GST 7.00/7.00% (S\$)	3,689.57	2,009.90	1,679.67	45.52
Nett Amount (S\$)	56,397.77	30,722.78	25,674.99	45.52

INSPECTION

Date of Assignment:	29/01/2020		
Date Inspected:	29/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,068.00 FS	*1,654.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	67.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	185.00 FS	*147.60 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	198.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	118.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,058.00 FS	*1,646.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Cracked	688.00 FS	*275.20 FS
9	1		*FRONT BUMPER CARRIER	Bent	757.00 FS	*605.20 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	117.00 FS	*93.60 FS
11	1		*FRONT BUMPER COVER	Deformed	120.00 FS	*96.00 FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	34.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS
14	1		*LOCK CARRIER	Cracked	129.00 FS	*103.20 FS
15	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	54.00 FS	*42.24 FS
16	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
17	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
18	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	55.00 FS	*- FS
19	1		*TEMPERATURE SENSOR BRACKET	Cracked	18.00 FS	*13.68 FS
20	1		*HORN - LH HIGH TONE	Not Necessary	38.00 FS	*- FS
21	1		*HORN - RH LOW TONE	Not Necessary	270.00 FS	*- FS
22	2		*SPRING SHACKLE - LH / RH	Not Necessary	54.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
24	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
25	1		*FRONT FENDER - RH	Buckled	722.00 FS	*577.60 FS
26	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
27	1		*FRONT FENDER CLOSING ELEMENT - RH	Bent	47.00 FS	*37.28 FS
28	1		*FRONT FENDER BRACKET - RH	Not Necessary	33.00 FS	*- FS
29	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	46.00 FS	*- FS
30	1		*FRONT FENDER BRACE - RH	Not Necessary	112.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	228.00 FS	*- FS
32	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	219.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*FRONT WHEEL SPOILER - RH	Not Necessary	69.00 FS	*- FS
34	1		*WHEEL SPOILER TRIM - RH	Not Necessary	34.00 FS	*- FS
35	1		*STONE CHIP GUARD - RH	Necessary	48.00 FS	*37.92 FS
36	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS
37	1		*BONNET ATTACHMENT PARTS	Not Necessary	388.00 FS	*- FS
38	2		*BONNET LID HINGE - LH / RH	Not Necessary	574.00 FS	*- FS
39	1		*BONNET IMPACT PROTECTION - CENTRE	Deformed	26.00 FS	*20.56 FS
40	1		*BONNET IMPACT PROTECTION - RH	Necessary	26.00 FS	*20.56 FS
41	1		*BONNET IMPACT PROTECTION - LH	Necessary	26.00 FS	*20.80 FS
42	1		*FENDER LEDGE COVER - RH	Not Necessary	29.00 FS	*- FS
43	1		*FENDER LEDGE TOP COVER	Not Necessary	21.00 FS	*- FS
44	2		*BONNET GAS FILLED STRUT	Not Necessary	224.00 FS	*- FS
45	2		*BONNET STRIKER - LH / RH	Not Necessary	94.00 FS	*- FS
46	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
47	1		*BONNET BOWDEN CABLE - CENTRE	Damaged	54.00 FS	*43.20 FS
48	1		*BONNET BOWDEN CABLE	Not Necessary	54.00 FS	*- FS
49	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
50	1		*BONNET LID LOCK CABLE	Not Necessary	69.00 FS	*- FS
51	1		*PLENUM CHAMBER COVER	Not Necessary	92.00 FS	*- FS
52	1		*BONNET SOUND ABSORBER	Not Necessary	323.00 FS	*- FS
53	2		*LED HEADLIGHT - LH / RH	Cracked	14,642.00 FS	*11,713.60 FS
54	1		*MAIN LIGHT ELECTRONIC POWER MODULE	Shorted	732.00 FS	*585.20 FS
55	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Shorted	707.00 FS	*565.60 FS
56	1		*HEADLIGHT HOSE - LH	Not Necessary	34.00 FS	*- FS
57	2		*HEADLAMP ASSEMBLY SPACER	Not Necessary	75.00 FS	*- FS
58	2		*HEADLAMP ASSEMBLY SPACER	Not Necessary	79.00 FS	*- FS
59	2		*LIFT CYLINDER - LH / RH	Not Necessary	396.00 FS	*- FS
60	1		*HEADLIGHT CORRUGATED PIPE	Not Necessary	88.00 FS	*- FS
61	1		*LOCK CARRIER	Not Necessary	956.00 FS	*- FS
62	2		*COOLANT REGULATOR SUPPORT	Not Necessary	71.00 FS	*- FS
63	1		*AIRCON CONDENSER	Bent	586.00 FS	*468.80 FS
64	1		*REFRIGERANT LINE PRESSURE SENDER	Not Necessary	179.00 FS	*- FS
65	1		*PRESSURE RELIEF VALVE	Not Necessary	49.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
66	1		*RADIATOR	Bent	766.00 FS	*612.40 FS
67	4		*READY MIX COOLANT	Not Necessary	169.00 FS	*- FS
68	2		*RADIATOR RUBBER BUSH - LOWER	Not Necessary	24.00 FS	*- FS
69	1		*CHARGE AIR COOLER	Not Necessary	552.00 FS	*- FS
70	1		*CHARGE AIR COOLER PRESSURE HOSE	Not Necessary	336.00 FS	*- FS
71	1		*CHARGE AIR COOLER PRESSURE PIPE - LH	Not Necessary	402.00 FS	*- FS
72	1		*RADIATOR FAN RING	Not Necessary	240.00 FS	*- FS
73	1		*RADIATOR FAN	Not Necessary	1,877.00 FS	*- FS
74	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	54.00 FS	*42.08 FS
75	2		*RADIATOR AIR GUIDE - LH	Cracked	24.00 FS	*17.76 FS
76	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	15.00 FS	*- FS
77	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	21.00 FS	*- FS
78	1		*AIR INTAKE AIR DUCT - RH	Not Necessary	21.00 FS	*- FS
79	1		*AIR INTAKE AIR GUIDE	Not Necessary	50.00 FS	*- FS
80	1		*AIR INTAKE AIR FILTER	Not Necessary	362.00 FS	*- FS
81	1		*AIR INTAKE AIR MASS METRE	Not Necessary	546.00 FS	*- FS
82	1		*AIR INTAKE HOSE	Not Necessary	90.00 FS	*- FS
83	1		*AIR INTAKE MANIFOLD	Not Necessary	651.00 FS	*- FS
84	4		*O-RING	Not Necessary	52.00 FS	*- FS
85	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
86	1		*SUNDRIES	Necessary	400.00 FS	*166.00 FS
87	1		*FRONT REINFORCEMENT BEAM BRACKET LH	Bent	171.20 FS	*171.20 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					39,906.20	21,940.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
3	TO REMOVE AND RENEW AIRCON CONDENSER AND RADIATOR. AND CHARGED AIR COOLER. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	350.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,250.00	3,250.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, LHS FRONT FENDER, BONNET, HINGES, BOTH A-UPPER PILLARS AND LHS FRONT DOOR	New	5,600.00	2,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			13,352.00	7,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >