

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20001594/R1GA3N2

Date: 22/05/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0006307
Claimant Vehicle No :	SKU6500T	Insured Vehicle No :	YP9755R
Date of Loss:	27/01/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0000232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU6500T		
Make & Model:	BMW 528I, 2.0 (A)	Engine No:	B3440887N20B20A
Reg. Date:	30/06/2015 (Man. Year: 2014)	Chassis No:	WBA5A52090D823593
Colour:	Grey	Odometer:	79441 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,582.24	4,858.69	723.55	12.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,825.00	9,894.00	1,931.00	16.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,407.24	14,752.69	2,654.55	15.25
+ GST 7.00/7.00% (S\$)	1,218.51	1,032.69	185.82	15.25
Nett Amount (S\$)	18,625.75	15,785.38	2,840.37	15.25
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,887.38		

INSPECTION

Date of Assignment:	11/02/2020	
Date Inspected:	11/02/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)
Parts:	143	BMW 528I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU6500T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	531.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	10		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	8.50 FS	*- FS
4	1		*RR LH FENDER (RH)	Bent	1,880.55 FS	*1,880.55 FS
5	1		*REINFORCEMENT PLATE C PILLAR RH	Necessary	53.75 FS	*53.75 FS
6	1		*REINFORCEMENT PLATE ROCKEL PANEL RH	Necessary	53.75 FS	*53.75 FS
7	1		*RR WINDOW GREEN	Necessary	921.00 FS	*921.00 FS
8	10		*BUMPER STOP	Not Necessary	37.50 FS	*- FS
9	1		*RR RH LIGHT IN SIDE PANEL	Broken	625.45 FS	*625.45 FS
10	1		*BLIND RIVET AVIBVLB (30 PCS)	Necessary	16.50 FS	*16.50 FS
11	1		*SCREW (SF PLUS M5X15)	Not Necessary	0.55 FS	*- FS
12	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
13	13		*PUNCH RIVET N5	Not Necessary	7.15 FS	*- FS
14	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Not Necessary	112.70 FS	*- FS
15	1		*(DG) CLEANER R1 (100ML) (2 PCS)	Necessary (1 PCS ONLY)	52.30 FS	*26.15 FS
16	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
17	1		*PUNCH RIVET N4 (40 PCS)	Necessary	22.00 FS	*22.00 FS
18	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
19	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
20	1		*3M S/F PREMIUM REAR WINDSCREEN	Necessary	252.34 FS	*252.34 FS
21	1		*RR RH MOUNT	Cracked	193.15 FS	*193.15 FS
22	1		*(S/L) CLEANER R2 500ML	Necessary	12.50 FS	*12.50 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **5,582.24** **4,858.69**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR RIGHT FENDER ,TAIL LAMP RIGHT ,ATTACHMENTS AND REPAIR REAR BUMPER	New	5,950.00	5,100.00
2	PAINTING REAR BUMPER ,REAR RIGHT FENDER ,ROOF FRAME AND TAIL PANEL	New	3,114.00	2,802.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
5	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS	New	531.00	0.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
7	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
8	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
Gross Labour Cost (\$\$)			11,825.00	9,894.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >