

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20001612/URS3Q2**Date:** 08/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBC1107E**Insured Vehicle No :** SLE7509K

Date of Loss: 19/12/2019

Nature of Claim:

TP

Claim No: 7313454470SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC1107E**

Make & Model: FIAT DOBLO CARGO MAXI, 1.6 MJ (A)

Engine No: 198A30006618545

Reg. Date: 25/05/2011 (Man. Year: 2011)

Chassis No: ZFA26300009094012

Colour: White

Odometer: 160981 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

Rear Tyre Size:

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	677.00	609.30	67.70	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	280.00	120.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,077.00	889.30	187.70	17.43
Approved Total (Overridden) (S\$)		700.00		
Nett Amount (S\$)	1,077.00	700.00	377.00	35.00
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		887.45		

INSPECTION

Date of Assignment: 28/01/2020

Date Inspected: 28/01/2020 Inspected At:

Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)

Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	627.00 F	*627.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					677.00	677.00
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	67.70
Total Parts (\$)					677.00	609.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	150.00	100.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	250.00	180.00
Gross Labour Cost (\$\$)			400.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >