



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706  Contact No	Cust No/Name KCV10835/Mr Ang Kheng Oon (hong Qing'En) Reg No/Reg Date SKP2229E / 27/03/2019 Date In/Mileage 23/01/2020/ 0 Chassis No GF7W0600738 Engine No 4J11AC8659 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim D01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000040	Credit	23/01/2020/ 18:29	DS	218 / MarsLer	40860		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
S	MIPNT88088	ZERTONA PAINT PROTECTION					550.00
S	MIPNT88088	ELECTRIC AUTO TAILGATE					1388.00
S	MIPNT88088	REVERSE SENSOR SET					280.00
S	MIPNT88088	TO REPLACE REAR REVERSE CAMERA LENS					350.00
M	SUNDRY	MIVEC EMBLEM					50.00
M	SUNDRY	C & C LOGO					50.00
S	MIPNT88088	DIAGNOSTIC / SCANNING					250.00
S	MIPNT88088	TO REPLACE TAILGATE GLASS					300.00
M	SUNDRY	SEALANT KIT ON TAILGATE GLASS					100.00
S	MIPNT88088	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS					220.00
S	MIPNT88088	TO TRANSFER TAILGATE COMPOMENT & MECHANISM PARTS					600.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL REAR CAPERTING AND TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS					600.00
S	MIPNT88088	TO REPLACE TAILGATE PNL,REAR BUMPER,REINFORCEMENT,ETC					4200.00
		-CUT & RE-WELD REAR END PANEL					
		-TO REPAIR REAR FLOORING PANEL					
		STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL					300.00
S	MIPNT88088						350.00

Confirm &amp; accepted by

12793

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name KCV10835/Mr Ang Kheng Oon (hong Qing'En) Reg No/Reg Date SKP2229E / 27/03/2019 Date In/Mileage 23/01/2020/ 0 Chassis No GF7W0600738 Engine No 4J11AC8659 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim D01 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000040	Credit	23/01/2020/ 18:29	DS	218 / MarsLer	40860
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
TO APPLY SOUND PROOF SEALANT ON REAR FLOOR PAN					2940.00
S MIPNT98088					
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					
M JJ6410D738	FACE,RR BUMPER	1.00	799.00	0.00	799.00
P JJ6415A090HA	EXTENSION,RR BUMPER	1.00	360.00	0.00	360.00
M JJMU488006	CLIP,BUMPER	10.00	2.00	0.00	20.00
P JJ6512A681	CLIP, RR BUMPER	30.00	6.00	0.00	180.00
P JJ6410D336	LH SIDE BRACKET, RR	1.00	12.00	0.00	12.00
P JJ6410D337	RH SIDE BRACKET, RR	1.00	12.00	0.00	12.00
M JJ6410B895	LH REINFORCEMENT,RR	1.00	79.00	0.00	79.00
M JJ6410B896	RH REINFORCEMENT,RR	1.00	79.00	0.00	79.00
P JJ7407A317	LH MOULDING, RR BUMP	1.00	106.00	0.00	106.00
M JJ7407A318	RH MOULDING, RR BUMP	1.00	106.00	0.00	106.00
P JJ8637A176	BUZZER, KEYLESS OPER	1.00	91.00	0.00	91.00
P JJ8637B115	ANTENNA, KEYLESS OPE	1.00	96.00	0.00	96.00
M JJ8518B072	HARNESS,RR BUMPER	1.00	84.00	0.00	84.00
M JJ8510J305	HARNESS,RR END	1.00	89.00	0.00	89.00
P JJ5257A967	PANEL,RR END	1.00	246.00	0.00	246.00
M JJ5801B673	TAILGATE PANEL ASSY	1.00	984.00	0.00	984.00
M JJ5817A265BA	GARNISH,TAILGATE	1.00	489.00	0.00	489.00
P JJ5815A067	WEATHERSTRIP, TAILGA	1.00	213.00	0.00	213.00
P JJ5805A306	GLASS,TAILGATE WINDO	1.00	751.00	0.00	751.00
P JJ5805A315	SIDE DAM,TAILGATE	2.00	27.00	0.00	54.00
P JJ5805A316	UPR DAM,TAILGATE	1.00	13.00	0.00	13.00
P JJ5805A317	LWR DAM,TAIL GATE	1.00	41.00	0.00	41.00
M JJMR462285	STOPPER,WINDSHIELD G	2.00	3.00	0.00	6.00
M JJMB814447	FASTENER,WINDSHIELD	4.00	6.00	0.00	24.00
P JJ7415A401	MARK,OUTLANDER	1.00	95.00	0.00	95.00
M JJ7240A290XA	TRIM,RR END	1.00	113.00	0.00	113.00
M JJ7646A187	BOX,CARGO FLOOR	1.00	204.00	0.00	204.00
M JJ7646A220	LID,CARGO FLOOR BOX	1.00	295.00	0.00	295.00
M JJ8336A153	LH REFLECTOR, TAIL L	1.00	100.00	0.00	100.00
M JJ8330B173	RR LH LAMP ASSY, COM	1.00	600.00	0.00	600.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706  Contact No	Cust No/Name KCV10835/Mr Ang Kheng Oon (hong Qing'En) Reg No/Reg Date SKP2229E / 27/03/2019 Date In/Mileage 23/01/2020/ 0 Chassis No GF7W0600738 Engine No 4J11AC8659 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim D01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000040	Credit	23/01/2020/ 18:29	DS	218 / MarsLer	40860

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M JJ8330B174 RR RH LAMP ASSY, COM	1.00	600.00	0.00	600.00
M JJ8331A179 LH TAIL LAMP ASSY	1.00	506.00	0.00	506.00
M JJ8331A180 RH TAIL LAMP ASSY	1.00	506.00	0.00	506.00
M JJ5808A119 LATCH, TAILGATE	1.00	383.00	0.00	383.00

Z NOTES

ACCIDENT ON 23/01/2020 ALONG SEMBAWANG ROAD

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # GBA9284J TP INS : LONPAC

# Estimate

Auto Consultants hence notify  
the Repairer of the following:

- To survey before/after spray painting
- To supply damaged part(s) during resurvey
- Prices are subject to confirmation
- This work is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

Parts	8,336.00
Labour	0.00
Standard Menu	0.00
Specialist Job	12,328.00
Others(Lub,etc)	0.00
Sundry	200.00
Total(w/o GST)	20,864.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706  Contact No	Cust No/Name	KCV10835/Mr Ang Kheng Oon (hong Qing'En)
	Reg No/Reg Date	SKP2229E / 27/03/2019
	Date In/Mileage	11/02/2020/ 19461
	Chassis No	GF7W0600738
	Engine No	4J11AC8659
	Make/Model	MIT/19MY OUTLANDER 2.0 ELEG (995)
	Colour/Trim	D01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000040	Credit	25/02/2020/ 16:54	DS	218 / MarsLer	40860
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	ZERTONA PAINT PROTECTION				550.00
S MIPNT88088	REVERSE SENSOR SET				280.00
M SUNDRY	MIVEC EMBLEM				50.00
M SUNDRY	C & C LOGO				50.00
S MIPNT88088	DIAGNOSTIC / SCANNING				250.00
S MIPNT88088	TO REPLACE TAILGATE GLASS				300.00
M SUNDRY	SEALANT KIT ON TAILGATE GLASS				100.00
S MIPNT88088	TO TRANSFER TAILGATE COMPOMENT & MECHANISM PARTS				300.00
S MIPNT88088	TO REMOVE AND RE-INSTALL REAR CAPERTING AND TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				300.00
S MIPNT88088	TO REPLACE TAILGATE PNL,REAR BUMPER,REINFORCEMENT,ETC				2700.00
	-CUT & RE-WELD REAR END PANEL				
	-TO REPAIR REAR FLOORING PANEL				
	STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				
S MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL				200.00
S MIPNT88088	TO APPLY SOUND PROOF SEALANT ON REAR FLOOR PAN				350.00
S MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				1890.00
X JJ6410F219	FACE,RR BUMPER	1.00	799.00	0.00	799.00
X JJ6415A090HA	EXTENSION,RR BUMPER	1.00	360.00	0.00	360.00
X JJMR200300	CLIP, BUMPER	10.00	2.00	0.00	20.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706  Contact No	Cust No/Name	KCV10835/Mr Ang Kheng Oon (hong Qing'En)
	Reg No/Reg Date	SKP2229E / 27/03/2019
	Date In/Mileage	11/02/2020/ 19461
	Chassis No	GF7W0600738
	Engine No	4J11AC8659
	Make/Model	MIT/19MY OUTLANDER 2.0 ELEG (995)
	Colour/Trim	D01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000040	Credit	25/02/2020/ 16:54	DS	218 / MarsLer	40860	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
X	JJ6512A681	CLIP, RR BUMPER	30.00	6.00	0.00	180.00
X	JJ6410D336	LH SIDE BRACKET, RR	1.00	12.00	0.00	12.00
X	JJ8510J305	HARNESS,RR END	1.00	89.00	0.00	89.00
X	JJ5801B673	TAILGATE PANEL ASSY	1.00	984.00	0.00	984.00
X	JJ5817A265BA	GARNISH,TAILGATE	1.00	489.00	0.00	489.00
X	JJ5805A306	GLASS,TAILGATE WINDO	1.00	751.00	0.00	751.00
X	JJ5805A315	SIDE DAM,TAILGATE	2.00	27.00	0.00	54.00
X	JJ5805A316	UPR DAM,TAILGATE	1.00	13.00	0.00	13.00
X	JJ5805A317	LWR DAM,TAIL GATE	1.00	41.00	0.00	41.00
M	JJMR462285	STOPPER,WINDSHIELD G	2.00	3.00	0.00	6.00
M	JJMB814447	FASTENER,WINDSHIELD	4.00	6.00	0.00	24.00
X	JJ7415A401	MARK,OUTLANDER	1.00	95.00	0.00	95.00
X	JJ7240A290XA	TRIM,RR END	1.00	113.00	0.00	113.00
X	JJ8330B173	RR LH LAMP ASSY, COM	1.00	600.00	0.00	600.00
X	JJ8331A179	LH TAIL LAMP ASSY	1.00	506.00	0.00	506.00
X	JJ8637A176	BUZZER, KEYLESS OPER	1.00	91.00	0.00	91.00
X	JJ5257A967	PANEL,RR END	1.00	246.00	0.00	246.00
Z	NOTES					
ACCIDENT ON 23/01/2020 ALONG SEMBAWANG ROAD						
OWNER CLAIMING THIRD PARTY						
REQUIRED REPLACEMENT CAR (R/A-22597)						
TP # GBA9284J TP INS : LONPAC						

Confirm &amp; accepted by

Parts	5,473.00
Labour	0.00
Standard Menu	0.00
Specialist Job	7,120.00
Others(Lub,etc)	0.00
Sundry	200.00
Total(w/o GST)	12,793.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.