Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001636/EKS3Q2

**Date:** 25/06/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SHB5025R Insured Vehicle No: SMN9178J

Date of Loss: 28/01/2020 Nature of Claim: TP Claim No: 3333993398SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHB5025R

Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZRS096342

Reg. Date: 10/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU503572615

Colour: Maroon Odometer: 47355 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,006.80	3,621.61	5,385.19	59.79
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,829.00	890.00	2,939.00	76.76
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	12,835.80	4,511.61	8,324.19	64.85
	+ Loss of Use (5.0 x	S\$50.00/day) (S\$)	250.00		
	+ Car Rental (5.0 x S	\$111.82/day) (S\$)	559.10		
	+ Doo	c/Search Fee (S\$)	7.00		
		Nett Liability (S\$)	5,327.71		
	Global Sur	m Settlement (S\$)	5,160.00		

**INSPECTION** 

Date of Assignment: 29/01/2020

Date Inspected: 29/01/2020 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: Khanchna Pothuraj

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER (DISC 25%)	Broken	495.50 F	*371.63 F
2	1		*SUPPORT ,FR BUMPER LH (DISC 25%)	Broken	82.30 F	*61.73 F
3	1		*FENDER SUB-ASSY ,FR LH (DISC 25%)	Dented	933.10 F	*699.83 F
4	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
5	1		*LINER ,FR FENDER ,LH (DISC 25%)	Torn	194.30 F	*145.73 F
6	1		*UNIT HEADLAMP LH (DISC 10%)	Cut	2,558.90 F	*2,303.01 F
7	1		*LAMP ASSY ,FOG LH	Not Necessary	910.20 F	*- F
8	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Not Necessary	486.40 F	*- F
9	1		*RETAINER ,FR FENDER NO.2	Not Necessary	16.80 F	*- F
10	1		*RETAINER ,FR FENDER NO.1	Not Necessary	4.90 F	*- F
11	1		*SUPPORT RADIATOR UPPER LH	Not Necessary	76.70 F	*- F
12	1		*APRON SUB-ASSY FRONT FENDER LH	Not Necessary	944.20 F	*- F
13	1		*BRACE SUB-ASSY FENDER APRON ,LH	Not Necessary	282.70 F	*- F
14	1		*SUPPORT S/A LH	Not Necessary	237.00 F	*- F
15	1		*WHEEL DISC FRONT	Not Necessary	1,555.10 F	*- F
16	1		*CAP SUB-ASSY ,WHEEL	Not Necessary	175.80 F	*- F
F=Franchise part.						2 624 64
				Total Parts (S\$)	9,006.80	3,621.61

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			-
1	PANEL BEATING & BODY WORK	New	845.00	350.00
2	SPRAY PAINT	New	2,034.00	450.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO APPLY RUST-PROOFING ON AFFECTED ARE	EA New	120.00	20.00
7	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	20.00
8	TO REPLACE SUNDRY PARTS	New	100.00	20.00
9	TO WASH AND VACUUM	New	60.00	0.00
	Gro	ss Labour Cost (S\$)	3,829.00	890.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.