Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001639/KHS3Q2

Date: 03/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800073597

Claimant
Vehicle No: SHD9231A

Insured Vehicle No: SMA2240B

Date of Loss: 25/01/2020 Nature of Claim: TP Claim No: 7716701459SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9231A

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C51975

Reg. Date: 30/08/2019 (Man. Year: 2018) Chassis No: JTDKB3FU403083400

Colour: Metallic Pearl White/Red Odometer: 63235 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 9 mm Rear Left Side: Goodyear 8 mm
Front Right Side: Sailun 9 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,108.65	1,723.90	9,384.75	84.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,000.00	950.00	13,050.00	93.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,108.65	2,673.90	22,434.75	89.35
+ GST 7.00/7.00% (S\$)	1,757.61	187.17	1,570.44	89.35
Nett Amount (S\$)	26,866.26	2,861.07	24,005.19	89.35
+ Loss of Use (3.0 x	S\$50.00/day) (S\$)	150.00		
+ Car Rental (3.0 x S	\$\$113.40/day) (S\$)	340.20		
+ Do	c/Search Fee (S\$)	7.49		
	Nett Liability (S\$)	3,358.76		
Global Su	m Settlement (S\$)	3,350.00		

INSPECTION

Date of Assignment: 29/01/2020

Date Inspected: 29/01/2020 Inspected At: Trans-Cab Services Pte Ltd (HQ)

2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	516.00 FL	*516.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	80.10 FL	*80.10 FL
3	1		*REINFORCEMENT ,FRONT BUMPER	Repair	716.60 FL	*- FL
4	1		*REINFORCEMENT ,FRONT BUMPER ,NO,2	Repair	246.10 FL	*- FL
5	1		*ABSORBER ,FRONT BUMPER ,LOWER	Serviceable	132.70 FL	*- FL
6	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
7	1		*COVER SUB-ASSY ,ENGINE ,NO.1	Serviceable	472.40 FL	*- FL
8	1		*COVER SUB-ASSY ,ENGINE UNDER ,NO.2	Serviceable	241.90 FL	*- FL
9	1		*EXTENSION ,FRONT BUMPER ,RH	Serviceable	120.10 FL	*- FL
10	1		*FRONT LED LAMP (LOWER) RH	Serviceable	951.40 FL	*- FL
11	1		*FRONT HEADLAMP RH	Serviceable	2,637.60 FL	*- FL
12	1		*COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	Serviceable	960.50 FL	*- FL
13	1		*MOTOR ,HEADLAMP LEVELING ,RH	Serviceable	487.50 FL	*- FL
14	1		*FRONT FENDER RH	Bent	977.80 FL	*977.80 FL
15	1		*LINER ,FRONT FENDER ,RH	Distorted	206.70 FL	*206.70 FL
16	1		*FRONT FENDER EMBLEM RH	Necessary	54.60 FL	*54.60 FL
17	1		*FRONT BONNET	Repair	983.10 FL	*- FL
18	1		*HINGE ASSY ,HOOD, RH	Repair	58.90 FL	*- FL
19	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	346.00 FL	*- FL
20	1		*EMBLEM ASSY ,RADIATOR GRILLE	Serviceable	90.80 FL	*-FL
21	1		*GRILLE ,RADIATOR ,LOWER NO .1	Serviceable	170.10 FL	*- FL
22	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	219.10 FL	*-FL
23	1		*MOTOR AND PUMP ASSY ,WINDSHIELD WASHER	Serviceable	292.40 FL	*-FL
24	1		*INLET SUB-ASSY ,WASHER	Serviceable	67.00 FL	*-FL
25	1		*FRONT WHEEL RIM	Serviceable	1,879.40 FS	*-FS
26	1		*FRONT WHEEL RIM COVER	Cracked	211.50 FS	*211.50 FS
27	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*-FS
28	1		*SET CLIP ,FRONT FENDER LINER	Necessary	35.00 FS	*35.00 FS
29	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*-FS
30	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
31	1		*SET FRONT BUMPER RETAINER CLIP	Necessary	35.00 FS	*35.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					0.400 = 0
Sub Total (S\$)					-	2,182.70
- List Item Discount on L Items 25.00/25.00% (S\$)					2,777.25	458.80
				Total Parts (S\$)	11.108.65	1,723.90

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	Labour Items						
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00			
2	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00			
3	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
4	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00			
5	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00			
7	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00			
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00			
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00			
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00			
11	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00			
	Gross Labour Cost (S\$)		14,000.00	950.00			
		,					

Report was unsubmitted during this print-out.

< END OF ESTIMATES >