

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20001642/AGS3Q2

Date: 17/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
**Claimant**  
**Vehicle No :** SLZ4771C **Insured Vehicle No :** SHA7852L  
**Date of Loss:** 23/01/2020 **Nature of Claim:** TP **Claim No:** MCT20010576

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ4771C**  
 Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: L15B5461927  
 Reg. Date: 03/05/2018 (Man. Year: 2018) Chassis No: GK81201646  
 Colour: Blue Odometer: 25394 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,621.00	4,979.84	3,641.16	42.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	2,030.00	1,440.00	41.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,091.00</b>	<b>7,009.84</b>	<b>5,081.16</b>	<b>42.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,091.00</b>	<b>5,600.00</b>	<b>6,491.00</b>	<b>53.68</b>
<b>+ Car Rental (10.0 x S\$100.00/day) (S\$)</b>		1,000.00		
<b>Nett Liability (S\$)</b>		<b>6,600.00</b>		

### INSPECTION

Date of Assignment: 29/01/2020  
 Date Inspected: 29/01/2020 Inspected At: Ysk Auto Workshop (HQ)  
 No.1 Kaki Bukit Avenue 6, #01-71  
 Autobay  
 Singapore 417883  
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Mar 2020)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ4771C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,460.80 FL	*1,195.00 FL
2	1		*SET TAILGATE GLASS MOULDING	Necessary	121.60 FL	*121.60 FL
3	1		*TAILGATE EMBLEM H	Not Necessary	42.20 FL	*- FL
4	1		*TAILGATE EMBLEM SHUTTLE	Necessary	58.80 FL	*58.80 FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	281.90 FL	*- FL
6	1		*TAILGATE CHROME MOULDING	Not Necessary	241.20 FL	*- FL
7	2		*TAILGATE LAMPS -L/R	Not Necessary	683.20 FL	*- FL
8	1		*TAILGATE INNER LOCK	Damaged	310.50 FL	*310.50 FL
9	1		*TAILGATE INNER TRIM BOARD	Cracked	411.90 FL	*411.90 FL
10	2		*TAILGATE STOPPERS	Not Necessary	25.20 FL	*- FL
11	1		*TAILGATE W/STRIP	Cut	161.90 FL	*161.90 FL
12	1		*TAILLAMP -LH	Cut	484.60 FL	*484.60 FL
13	1		*REAR BUMPER	Deformed	1,210.60 FL	*1,050.00 FL
14	1		*REAR BUMPER SIDE COVERS -L/R	N/S Deformed	220.40 FL	*110.20 FL
15	1		*REAR BUMPER INNER SPONGE -L/R	N/S Cracked	137.20 FL	*68.60 FL
16	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
17	2		*REAR BUMPER SIDE RETAINER -L/R	Necessary	131.00 FL	*131.00 FL
18	1		*REAR END PANEL	Distorted	680.90 FL	*680.90 FL
19	1		*REAR END PANEL TRIM	Deformed	241.20 FL	*241.20 FL
20	2		*REAR FLOOR BOARD	Not Necessary	380.90 FL	*- FL
21	1		*REAR FLOOR COMPARTMENT TRAY	Deformed	461.60 FL	*461.60 FL
22	1		*REAR FLOOR COMPARTMENT TRAY COVER	Not Necessary	189.90 FL	*- FL
23	1		*REAR FLOOR COMPARTMENT PANEL	Repair	911.40 FL	*- FL
24	1		*REAR FENDER INNER TRIM BOARD -LH	Cracked	681.60 FL	*335.00 FL
25	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
26	1		*SET TAILGATE GLASS FOAM TAPE	Necessary	65.00 FS	*40.00 FS
27	1		*REAR REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
28	1		*SET REAR REVERSE SESOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,532.50</b>	<b>6,149.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,911.50	1,169.96
<b>Total Parts (\$\$)</b>	<b>8,621.00</b>	<b>4,979.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
2	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
3	TO REMOVE,REFIX REAR INTERIOR TRIM TO ASSIST REPAIR	New	150.00	60.00
4	TO REMOVE,REFIX REAR REVERSE SENSOR /CAMERA	New	120.00	80.00
5	REINSTALL TAILGATE ELECTRICAL & COMPONENTS TO NEW TAILGATE	New	150.00	80.00
6	TO RESPRAY UNDERCOATING	New	120.00	60.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
8	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,470.00</b>	<b>2,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >