




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI20001643/Upa3s2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 06-08-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 6584H	Veh. Inspected	SKL 9054S
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM20HO00195/JT	Excess (\$)	0.00
	Assign From	JAIME TAY	Assign Date	29/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS LS460 (A)	c.c	4608
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JTHBL46F405127385	Colour	SILVER
	Odometer	251018	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	CONTINENTAL	7 mm
	L/H Front Tyre	235/50 R18	CONTINENTAL	7 mm
	R/H Rear Tyre	235/50 R18	CONTINENTAL	7 mm
	L/H Rear Tyre	235/50 R18	CONTINENTAL	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION AND FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/01/2020	Inspection Date	31/01/2020
	Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	