



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SJW2919Y TOYOTA VIOS 1.5A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>		Less 25%		
1	Rear bumper / de		340.00	485.5
1	Bootlid X Repair		450.00	
1	End panel cover X BE NN		90.00	
1	End panel X Repair		380.00	
1	Taillamp RH X NN		180.00	
1	Rear reflector RH X NN		75.00	
1	Rear fender RH X		390.00	
1	Rear side retainer RH / de		65.00	
1	Rear innershield RH X NN		170.00	
			2140.00	
			535.00	
			1605.00	
<u>SPECIAL NETT ITEMS</u>		Total Parts		
1	Rear bumper clips / MC		30.00	150.
1	Rear innershield clips X NN		25.00	
1	End panel cover clips X		20.00	
1	Reverse sensor / DM	220.00		
			1900.00	

180

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SJW2919Y TOYOTA VIOS 1.5A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1000.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	500
3	To remove and re-fix wiring and check all electrical components	150.00	30
4	To provide anti-rust treatment on affected area	150.00	X NaN
Labour Total :		2100.00	
TOTAL (PARTS & LABOUR):		4000.00	

830

3 Days.

Imp sum repair.

After repair photos.

Gm O Qiang - 82880282

31/11/2020.

1299.12
20%: 1000