

NA2


REF: FCI

## ASSIGNMENT

From: \_\_\_\_\_ Date: 30/11/2020  
 Estimated Cost: \_\_\_\_\_  
 DD: TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SHC 6856Y  
 at Workshop m/s: Premier Automotive  
 of 23 Changi South Avenue 2 #01-02  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHC 6856Y (vs Regs: 2 SEP 2015)  
 Type: M/Car / M/Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: KIA OPTIMA

Colour: SILVER

Sp. Reading: 43,822

Eng No: \_\_\_\_\_

C No: KNAGM414MF5619998

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achillies

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 27/10/2020 D.O.I: 30/11/2020

Survey held at: PREMIER CHANGI

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prel. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: \_\_\_\_\_ Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Week end (\$)

S + RS \$

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / LBJ: (\$)

**Enquire Transaction History**

## Transaction History Details

Log Date/Time: 02 Sep 2015 / 08:05:01

Asset Type: Vehicle

Asset ID: SHC6856Y

Transaction Type: 01.02 Register New Vehicle (AA)

Business Transaction Reference No.: 201509020805018674C8

Receipt No.:

AACCK001-AX239-150902-000021

Transaction Amount:

\$69,132.00

Channel:

AA Counterless - CYCLE &amp; CARRIAGE KIA PTE LTD

Vehicle No.: SHC6856Y  
Vehicle Type: H10 - Public Transport Taxi (Motor Car)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Scheme: Taxi (Company)  
First Registration Date: 02 Sep 2015  
Original Registration Date: 02 Sep 2015  
Vehicle Make: KIA  
Vehicle Model: OPTIMA 1.7(A) DIESEL  
Chassis No.: KNAGM414MF5619948  
Engine No.: D4FDEH313527  
Motor No.: -  
Trailer Chassis No.: -  
Propellant: Diesel  
Passenger Capacity: 4  
Engine Capacity: 1685  
Power Rating: -  
Unladen Weight: 1584  
Maximum Laden Weight: 2050  
Primary Color: Silver  
Secondary Color: -  
Manufacturing Year: 2015  
Open Market Value: \$21,156.00  
Minimum PARF Benefit: \$12,971.00  
PARF Eligibility: Y  
No. of Transfer: 0  
Effective Ownership Date/Time: 02 Sep 2015 08:05:01  
COE No.: 2015090201003474G  
COE Expiry Date: 01 Sep 2023  
COE Bid Category: -  
Actual QP/PQP Paid Amount: \$47,373.00  
Lifespan Expiry Date: 01 Sep 2023

# **PREMIER AUTOMOTIVE SERVICES PTE LTD**

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

29-Jan-20

## **ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y**

|       |                                                   |
|-------|---------------------------------------------------|
| 1 pc  | Boot lid                                          |
| 1 pc  | Boot lid lock                                     |
| 1 pc  | Bootlid lock cable                                |
| 1 pc  | Bootlid striker                                   |
| 1 pc  | Bootlid emblem                                    |
| 1 pc  | Bootlid CRDi                                      |
| 1 pc  | Boot lid rubber weatherstrip                      |
| 1 pc  | Boot lid lower garnish                            |
| 2 pcs | Bootlid hinges @ \$66.00                          |
| 1 pc  | Bootlid inner trim                                |
| 2 pcs | Rear license plate lamps @ \$30.00                |
| 1 pc  | End panel                                         |
| 1 pc  | End panel inner garnish                           |
| 2 pcs | Rear o/s & n/s fender inner shield @\$120.00      |
| 1 pc  | Rear bumper                                       |
| 1 pc  | Rear bumper lower cover                           |
| 2 pcs | Rear bumper side bracket o/s & n/s @ \$29.00      |
| 1 pc  | Rear bumper inner sponge                          |
| 1 pc  | Rear bumper reinforcement                         |
| 2 pcs | Rear bumper stay o/s & n/s @ \$53.00              |
| 2 pcs | Rear bumper reinforcement lower bracket @ \$18.00 |
| 2 pcs | Rear bumper reinforcement upper bracket @ \$18.00 |
| 2 pcs | Rear bumper reflector n/s & o/s @ \$46.00         |
| 2 pcs | n/s & o/s tail lamp @ \$421.00                    |
| 2 pcs | n/s & o/s reflector @ \$350.00                    |
| 2 pcs | n/s & o/s tail lamp panel @ \$215.00              |
| 1 pc  | Exhaust pipe hanger                               |
| 1 pc  | Floorboard panel trim                             |
| 1 pc  | Exhaust pipe                                      |

|          |          |                   |
|----------|----------|-------------------|
| \$       | 1,119.00 | XR                |
| \$       | 99.00    | XSVL              |
| \$       | 35.00    | ?                 |
| \$       | 21.00    | XSVL              |
| \$       | 27.00    | NE                |
| \$       | 29.00    | NEL               |
| \$       | 96.00    | DBF               |
| \$       | 290.00   | ?                 |
| \$       | 132.00   | ?                 |
| \$       | 190.00   | ?                 |
| \$       | 60.00    | XSVL              |
| \$       | 250.00   | BT                |
| \$       | 74.00    | ?                 |
| \$       | 240.00   | RH/TN<br>LHX SVL  |
| \$       | 696.00   | CRK               |
| \$       | 206.00   | CRK               |
| \$       | 58.00    | ?                 |
| \$       | 114.00   | ?                 |
| \$       | 607.00   | ?                 |
| \$       | 108.00   | ?                 |
| \$       | 36.00    | ?                 |
| \$       | 36.00    | ?                 |
| \$       | 92.00    | SCR               |
| \$       | 842.00   | RH CRK<br>LHX SVL |
| \$       | 700.00   |                   |
| \$       | 430.00   | ?                 |
| \$       | 28.00    | ?                 |
| \$       | 205.00   | XSVL              |
| \$       | 1,009.00 | DBF               |
| \$       | 7,829.00 |                   |
| Less 10% | \$       | 782.90            |
|          | \$       | 7,046.10          |

29-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y

S/NETT

1 set Rear bumper clips  
1 set End panel inner garnish clips  
1 set Bootlid inner trim clips  
1 set Bootlid lower garnish clips  
1 set Bootlid stickers  
1 set Reverse sensor  
1 set Rear bumper top protector  
1 pc Floorboard compartment insulating paddings  
1 set Rear no. plate with casing  
1 pc Sealant  
1 set 24 fender rear shaker  
Sundry  
Towing fee  
To dismantle & refit the exhaust pipe

\$ 48.00 /NEC  
\$ 30.00 ?  
\$ 52.00 ?  
\$ 60.00 ?  
\$ 100.00 /NEC  
\$ 280.00 XSVL  
\$ 80.00 X no such item  
\$ 120.00 ?  
\$ 50.00 XSVL  
\$ 50.00 XNN  
\$ 30 /NEC  
\$ 50.00 XNN  
NN X \$ 50.00 ? SWW  
\$ 150.00 60

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 120.00 30

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 480.00 50

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear o/s fender, n/s & o/s taillamp panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc

540 720  
\$ 1,400.00 540

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s tail lamp panel, rear o/s tail lamp panel,

\$ 1,400.00 900

To apply rustproofing on the repaired and replaced panels.

\$ 300.00 100  
\$ 11,566.10

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK 30/1/2020 1930  
LCS

6 DAYS  
CHECK ITEM PHOTOS  
APPROPRIATE PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: