



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204425

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/07/2022
Reference CC3/CTI20001673/Nea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 7338E
Insured Veh. GBF 4547H
Claim No. SNM20D200525
Policy No. DMCVSN3080921902
Accident Date 24/01/2020
Inspection Date 29/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20001673/Nea3q2	
			Date: 20/07/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 4547H	Veh. Inspected	SHA 7338E	
Policy No.	DMCVSN3080921902	Coverage (\$)	0.00	
Claim No.	SNM20D200525	Excess (\$)	0.00	
Assign From		Assign Date	29/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU203080866	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	POOR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	5 mm	
L/H Front Tyre	195/65 R15	DAVANTI	5 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/01/2020	Inspection Date	29/01/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7338E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	950.50	950.50
1	INSULATOR, HOOD	SERVICEABLE	398.10	-
10	INSULATOR CLIPS @ \$3.60	SERVICEABLE	36.00	-
1	BONNET RUBBER	SERVICEABLE	35.50	-
1	BONNET CABLE	SERVICEABLE	53.20	-
1	BONNET HINGE (RH)	BENT	57.70	57.70
1	BONNET HINGE (LH)	BENT	57.70	57.70
1	BONNET LOCK	SERVICEABLE	132.60	-
1	CATCH, HOOD AUXILIARY HOOK	SERVICEABLE	8.60	-
1	RADIATOR GRILLE	SERVICEABLE	438.00	-
1	RADIATOR GRILLE EMBLEM	SERVICEABLE	88.00	-
1	LAMP ASSY, FOG, LH	MISSING	920.00	920.00
1	FRONT BUMPER COVER	CRACKED	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	BENT	696.40	696.40
1	FRONT BUMPER SPONGE	DEFORMED	78.80	78.80
1	FRONT BUMPER CENTRE GRILLE	SERVICEABLE	301.90	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	166.90	-
10	FRONT BUMPER CLIPS @ \$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE RETAINER LH	MISSING	77.00	77.00
1	FRONT LOWER CROSSMEMBER	DEFORMED	357.70	357.70
1	FRONT RADIATOR LOWER SUPPORT PANEL	SERVICEABLE	357.70	-
1	FRONT UNDER COVER	SERVICEABLE	180.80	-
1	ENGINE UNDER COVER	SERVICEABLE	457.40	-
1	FRONT BUMPER TOP GARNISH	SERVICEABLE	225.40	-
1	COVER, FRONT BUMPER HOLE, LH	CRACKED	28.38	28.38
1	SUPPORT FR BUMPER, LH	DEFORMED	81.70	81.70
1	FRONT BUMPER CENTRE FRAME	SERVICEABLE	236.90	-
1	BRACKET, FRONT BUMPER SIDE, LH	SERVICEABLE	82.30	-
1	BRACKET, FRONT BUMPER MOUNTING LH	SERVICEABLE	29.60	-
1	BRACKET, FRONT BUMPER MOUNTING, NO.2 LH	SERVICEABLE	97.80	-
1	ABSORBER, FRONT BUMPER, LOWER LH	SERVICEABLE	127.70	-

Report Ref No. CC3/CTI20001673/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	UNIT ASSY, HEADLAMP, LH (LED)	CRACKED	3,455.00	3,455.00
1	HEAD LAMP PANEL (LH)	SERVICEABLE	240.10	-
1	TO PANEL CENTRE	SERVICEABLE	364.90	-
1	TOP PANEL SIDE LH	SERVICEABLE	145.90	-
1	BRACKET, HEADLAMP MOUNTING, LH	SERVICEABLE	25.50	-
1	RADIATOR ASSY	SERVICEABLE	1,881.30	-
1	RADIATOR FAN COWLING ASSY	SERVICEABLE	661.30	-
1	RADIATOR TOP HOSE, LH	SERVICEABLE	43.03	-
1	RADIATOR TOP HOSE, RH	SERVICEABLE	42.60	-
1	RADIATOR SPARE TANK	SERVICEABLE	125.80	-
1	RADIATOR BOTTOM MOUNTING	SERVICEABLE	27.50	-
1	STAY, RADIATOR SUPPORT, RH	SERVICEABLE	65.70	-
1	STAY, RADIATOR SUPPORT, LH	SERVICEABLE	65.70	-
1	RADIATOR FAN BLADE (RH)	SERVICEABLE	233.10	-
1	RADIATOR FAN BLADE (LH)	SERVICEABLE	233.10	-
1	RADIATOR FAN MOTOR (RH)	SERVICEABLE	543.70	-
1	RADIATOR FAN MOTOR (LH)	SERVICEABLE	543.70	-
1	DEFLECTOR, RADIATOR SIDE, RH	SERVICEABLE	83.50	-
1	DEFLECTOR, RADIATOR SIDE, LH	SERVICEABLE	77.00	-
1	COVER, RADIATOR SUPPORT OPENING	SERVICEABLE	225.40	-
1	AIR CLEANER TOP COVER	SERVICEABLE	446.50	-
1	AIR CLEANER BOTTOM COVER	SERVICEABLE	947.80	-
1	AIR CLEANER HOSE	SERVICEABLE	62.12	-
1	AIR DUCT	SERVICEABLE	129.40	-
1	INLET ASSY, AIR CLEANER	SERVICEABLE	132.00	-
1	AIR DUCT CENTRE	SERVICEABLE	94.03	-
1	AIRCON CONTROL ASSY	SERVICEABLE	867.70	-
1	CONDENSER ASSY, W/RECEIVER	SERVICEABLE	1,336.60	-
1	AIRCON DISCHARGE HOSE	SERVICEABLE	386.90	-
1	AIRCON LIQUID HOSE & PIPE	SERVICEABLE	580.45	-
1	AIRCON HOSE SUCTION	SERVICEABLE	548.50	-
1	FENDER SUB-ASSY, FRONT LH	DEFORMED	945.30	945.30
1	FRONT HOUSING ASSY, LH	DEFORMED	958.30	958.30

Report Ref No. CC3/CTI20001673/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER SHIELD, LH	MISSING	196.60	196.60
10	FRONT FENDER SHIELD CLIPS @ \$3.80	NECESSARY	38.00	38.00
1	FRONT FENDER HYBRID EMBLEM, LH	NECESSARY	53.50	53.50
1	BRACKET, FRONT SIDE PANEL, LH	SERVICEABLE	44.50	-
1	EXTENSION, FRONT FENDER, LH	SERVICEABLE	47.20	-
1	PROTECTOR, FRONT FENDER, UPPER, LH	SERVICEABLE	46.10	-
1	GUSSET, FRONT FENDER APRON, LOWER LH	SERVICEABLE	34.90	-
1	FRONT APRON TO COWL SIDE, UPPER LH	SERVICEABLE	138.40	-
1	FRONT APRON TO COWL SIDE, LWR FRONT LH	SERVICEABLE	82.30	-
1	TRAY, BATTERY	SERVICEABLE	42.80	-
1	CLAMP, BATTERY	SERVICEABLE	58.00	-
1	PANEL SUB-ASSY, FRONT DOOR, LH	DEFORMED	1,264.00	1,264.00
1	FRONT DOOR GLASS LH	NECESSARY	313.60	313.60
1	FRONT DOOR OUTER HANDLE (LH)	SERVICEABLE	378.90	-
1	FRONT DOOR HINGE UPPER	SERVICEABLE	82.30	-
1	FRONT DOOR HINGE LOWER	SERVICEABLE	91.20	-
1	REAR DOOR, LH	DEFORMED	1,258.30	1,258.30
1	REAR DOOR OUTER HANDLE LH	SERVICEABLE	93.90	-
1	WIING MIRROR LH	BROKEN	1,390.10	1,390.10
1	WING MIRROR COVER LH	SCRATCHED	141.90	141.90
1	WING MIRROR DELTA COVER LH	SCRATCHED	212.80	212.80
1	FRONT PILLAR UPPER COVER, LH	SERVICEABLE	96.00	-
1	FRONT WINDSCREEN GLASS	SERVICEABLE	1,627.30	-
1	FRONT WINDSCREEN GLASS MOULDING	SERVICEABLE	208.60	-
1	FRONT WINDSCREEN GLASS PILLAR LH	SERVICEABLE	343.10	-
1	WIPER COWL PANEL	DEFORMED	183.75	183.75
1	FRONT WHEEL RIM LH	TO REPAIR SEE LABOUR	1,555.10	-
2	FRONT & REAR WHEEL HUB CAP LH @ \$177.70	SCRATCHED	355.40	355.40
1	FRONT WHEEL HUB BEARING LH	SERVICEABLE	560.10	-
1	FRONT SHOCK ABSORBER (LH)	SERVICEABLE	401.80	-
1	ABSORBER TOP MOUNTING, LH	SERVICEABLE	196.20	-
1	FRONT SUSPENSION LOWER ARM (LH)	SERVICEABLE	637.50	-

Report Ref No. CC3/CTI20001673/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	KNUCKLE, STEERING, LH	SERVICEABLE	562.30	-
1	HUB SUB-ASSY, FRONT AXLE, LH	SERVICEABLE	549.70	-
1	END SUB-ASSY, TIE ROD, LH	SERVICEABLE	158.10	-
1	ENGINE UNDER COVER	SERVICEABLE	457.20	-
1	ENGINE CROSS MEMBER	SERVICEABLE	2,531.70	-
1	ROCKER PANEL GARNISH LH	SERVICEABLE	559.20	-
1	REAR FENDER LH	DEFORMED	836.70	836.70
2	FRT FENDER PIN HOLDER LH @ \$1.30 (ADDITIONAL)	MISSING	2.60	2.60
2	FRT FENDER SHIELD RETAINER LH @ \$16.80 (ADDITIONAL)	MISSING	33.60	33.60
1	ENGINE MAIN WIRE HARNESS (ADDITIONAL)	DAMAGED	6,138.00	6,138.00
1	F/BUMPER REINFORCEMENT LH (ADDITIONAL)	MISSING	236.00	236.00
1	BATTERY 12V58AH METADOR (ADDITIONAL)	DAMAGED	340.00	340.00
1	HEADLAMP MODULE LH (ADDITIONAL)	DAMAGED	481.40	481.40
1	FRT WINDSCREEN MTG CLIP LH (ADDITIONAL)	MISSING	8.70	8.70
1	FRT BUMPER SIDE BRKT LH (ADDITIONAL)	MISSING	56.01	56.01
1	FRT FENDER EXTENSION LH (ADDITIONAL)	MISSING	47.17	47.17
1	FOGLAMP LH (ADDITIONAL)	REPEATED	920.00	-
1	BONNET HINGE RH (ADDITIONAL)	REPEATED	57.70	-
	LESS 25% DISCOUNT		-12,487.96	-5,693.63
			37,463.88	17,080.88
	<u>SPECIAL NETT ITEMS</u>			
1	ERP STICKER (SN)	NOT NECESSARY	26.00	-
1	FRONT DOOR COMFORTDELGRO LH (SN)	NECESSARY	75.00	75.00
1	REAR DOOR APPS LH (SN)	NECESSARY	80.00	80.00
2	FRONT WINDSCREEN SEALANT @ \$46.00 (SN)	NOT NECESSARY	92.00	-
1	FRT DAVANTI TYRE LH (SN) (ADDITIONAL)	DAMAGED	216.00	129.60
			489.00	284.60
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT WHEEL RIM LH.		2,400.00	1,600.00
	SPRAY PAINTING CHARGE.		1,750.00	1,200.00
	WIRING CHARGE.		120.00	50.00

Report Ref No. CC3/CTI20001673/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		200.00	100.00
	TOWING CHARGE - KING DOLLY.	NOT NECESSARY	200.00	-
	FRONT CHASSIS ALIGNMENT CHARGE.		400.00	200.00
	REMOVE / REFIX CUSHIO & UPHOLSTERY.		150.00	30.00
	REMOVE / REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TRANSFER OF DOORS (BOTH LEFT).		240.00	100.00
	REMOVE / REFIX UNDERCARRIAGE (FRT).		300.00	150.00
	WHEEL ALIGNMENT.		120.00	100.00
	REMOVE / REFIX ENGINE ASSY.	NOT NECESSARY	450.00	-
	REMOVE / REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	REMOVE / REFIX STEERING RACK / WHEEL / DR SHAFT.	NOT NECESSARY	500.00	-
	DIAGNOSIS & RESETTING TO ORIGINAL SPECS.	NOT NECESSARY	480.00	-
	WHEEL ALIGNMENT. (ADDITIONAL)		100.00	100.00
	R/I FUSE BOX. (ADDITIONAL)	REPEATED	100.00	-
	R/I DASHBOARD / RESET TO SPECS. (ADDITIONAL)		400.00	400.00
			8,180.00	4,030.00
GRAND TOTAL			46,132.88	21,395.48

RECOMMENDED COST OF REPAIRS			21,395.48
------------------------------------	--	--	------------------

Report Ref No. CC3/CTI20001673/Nea3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7338E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7338E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7338E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

