

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 223T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	DENTED	482.00	361.50
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BRACKET ,FR BUMPER (DISC 25%)	BROKEN	110.40	82.80
1	NUMBER PLATE FRAME (SN)	BROKEN	12.00	12.00
1	NUMBER PLATE (SN)	BENT	15.00	15.00
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY ,FR BUMPER LH	NOT NECESSARY	250.40	-
1	BUMPER GRILLE SUB-ASSY LOWER	NOT NECESSARY	311.10	-
1	GRILLE RADIATOR	NOT NECESSARY	310.60	-
1	HEAD LAMP LH	NOT NECESSARY	945.20	-
1	BRACKET ,FR BUMPER	NOT NECESSARY	110.40	-
1	COVER ,FR BUMPER HOLE LH	TO REPAIR SEE LABOUR	18.50	-
			3,321.80	548.26
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF COVER ,FR BUMPER HOLE LH .		507.00	200.00
	SPRAY PAINT.		558.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			-	-
			-	-
			-	-
			1,305.00	450.00
	GRAND TOTAL		4,626.80	998.26

Report Ref No. CC3/QBE20001679/Eea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC3/QBE20001679/Eea3q2

and the second

CHEN TSUE YEE

Automotive Assessor

/monto

HO LEONG CHUAN

Automotive Assessor