



Case Details

Case Reference Number : TAX/01/20/2110
Type of Repair : Accident Repair
Vehicle Registration Number : SHB223T

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-10252-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : QBE Insurance (International) Ltd
Accident Date and Time : 26/01/2020 04:25 AM
Vehicle Age(In Months) : 75

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	✓ 00
Standard	Main		6505516	BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	✗ NN
Standard	Main		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	✗ NN
Standard	Main		6505539	BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	✗ NN
Standard	Main		6505544	ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	✗ NN
Standard	Main		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Check	✗ NN
Standard	Main		6505638	EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	1	64.88	Replace	✓ MK
Standard	Main		6505573	GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give	✗ NN
Standard	Main		6505436	HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ MK
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	✓ BR
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	✓ BT
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	0	Repair	✗ R
Total Spare Part Cost									2,557.10	Surveyor Total 465.46				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									2,045.68	Final Sur Total 465.46				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	MPK
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	MPK
3	Main	TO WASH AND VACUUM	60.00	0	
Total:			240.00	50.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,045.68	465.46
Total Labour Cost	507.00	200.00
Total Spray Painting	558.00	200.00
Other	240.00	50.00
Overall Total	3,350.68	915.46
Lump Sum Repair Option		☒
Lump Sum Total	3,350.00	900.00
Surveyor Approved Amount		900.00
No of Repair Days*	4	2
Remarks		L/S repair, take after spray.
Surveyor Name		STEVE CHEN

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save

Clear

Survey Date

29/01/2020

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: