

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001680/KES3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLT2463L **Insured Vehicle No :** SKE5567S

Date of Loss: 27/01/2020 Nature of Claim: TP Claim No: 5311340262SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT2463L	Engine No:	2ZR0A24304
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W80J008089
Reg. Date:	24/10/2017 (Man. Year: 2017)	Odometer:	136472 km
Colour:	Metallic Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Gremax 8 mm	Rear Left Side:	Gremax 7 mm
Front Right Side:	Gremax 8 mm	Rear Right Side:	Gremax 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,845.98	4,264.42	3,581.56	45.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,740.00	1,390.00	44.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,975.98	6,004.42	4,971.56	45.29
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	10,975.98	4,800.00	6,175.98	56.27
+ GST 7.00/7.00% (S\$)	768.32	336.00	432.32	56.27
Nett Amount (S\$)	11,744.30	5,136.00	6,608.30	56.27
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,983.45		
Global Sum Settlement (S\$)		5,980.00		

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 30/01/2020 Inspected At:

COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,550.00 FL	*1,209.00 FL
2	1		*TAIL GATE LOCK	Dented	361.61 FL	*333.10 FL
3	1		*TOYOTA LOGO	Necessary	66.20 FL	*66.20 FL
4	1		*TAIL GATE CHROME GARNISH	Cracked	487.60 FL	*288.90 FL
5	2		*TAIL GATE REFLECTOR	Serviceable	614.80 FL	*- FL
6	1		*TAIL GATE RUBBER SEA	Cut	358.70 FL	*358.70 FL
7	1		*TAIL LAMP	O/S Cracked	921.80 FL	*360.20 FL
8	1		*REAR BUMPER	Bent	665.70 FL	*633.50 FL
9	2		*REAR BUMPER BRACKET	Repair	114.00 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINER	Distorted	202.00 FL	*202.00 FL
11	2		*REAR BUMPER REFLECTOR	Serviceable	165.20 FL	*- FL
12	1		*REAR BUMPER SPONGE	No such part	195.60 FL	*- FL
13	8		*REAR BUMPER CLIP	Necessary	44.00 FL	*44.00 FL
14	1		*REAR END PANEL	Bent	540.20 FL	*540.20 FL
15	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	310.80 FL	*255.30 FL
16	2		*REAR END PANEL DAMPER	Serviceable	134.00 FL	*- FL
17	1		*SPARE TIRE PANEL	Repair	725.10 FL	*- FL
18	1		*SPARE TIRE LATCH LOCK	Repair	298.20 FL	*- FL
19	1		*REAR EXHAUST PIPE	Bent	756.20 FL	*756.20 FL
20	2		*REAR EXHAUST MOUNTING	Serviceable	127.00 FL	*- FL
21	1		*REAR END PANEL IMMOBILIZER SENSOR	Cracked	173.00 FL	*173.00 FL
22	2		*REAR W/SCREEN MOULDING SIDE	Necessary	150.60 FL	*150.60 FL
23	1		*REAR W/SCREEN MOULDING UPPER	Necessary	72.50 FL	*72.50 FL
24	1		*REAR W/SCREEN MOULDING BOTTOM	Necessary	72.10 FL	*72.10 FL
25	1		*TAIL GATE REAR W/SCREEN SEALANT	Necessary	65.00 FS	*40.00 FS
26	1		*TAIL GATE REVERSE CAMERA	Serviceable	850.00 FS	*- FS
27	1		*VALVE MATIC EMBLEM	Necessary	42.80 FS	*42.80 FS
28	1		*REAR NUMBER PLATE +HOLDER	Dented	58.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,122.71	5,643.30
- List Item Discount on L Items 25.00/25.00% (\$)	2,276.73	1,378.88
Total Parts (\$)	7,845.98	4,264.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REINSTALL REAR W/SCREEN GLASS	New	180.00	120.00
2	TRANSFER TAILGATE COMPONENT TO NEW GATE	New	150.00	60.00
3	RUST PROOFING TREATMENT	New	100.00	60.00
4	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,300.00	800.00
5	TO CUT OFF REAR END PANEL,SPARE TIRE PANEL ,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	New	1,400.00	700.00
Gross Labour Cost (S\$)			3,130.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >