

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001683/QES3Q2

Date: 17/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100071077

Claimant
Vehicle No : SLE6123X **Insured Vehicle No :** SDW818P

Date of Loss: 27/01/2020 Nature of Claim: TP Claim No: 0992568654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE6123X		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5908474
Reg. Date:	27/07/2016 (Man. Year: 2016)	Chassis No:	RU31208464
Colour:	Brown	Odometer:	244307 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Neuton 5 mm	Rear Left Side:	Neuton 5 mm
Front Right Side:	Neuton 5 mm	Rear Right Side:	Neuton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,599.68	6,256.88	3,342.80	34.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	2,410.00	630.00	20.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,639.68	8,666.88	3,972.80	31.43
Approved Total (Overridden) (S\$)		6,950.00		
(S\$)	12,639.68	6,950.00	5,689.68	45.01
+ GST 7.00/7.00% (S\$)	884.78	486.50	398.28	45.01
Nett Amount (S\$)	13,524.46	7,436.50	6,087.96	45.01
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		160.50		
Nett Liability (S\$)		8,019.00		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 30/01/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-01 Carros
Centre
Singapore 737869

Estimated Period of Repair: 7.0 days

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,450.00 FL	*1,283.00 FL
2	1		*REAR TAILGATE BACK DOOR TRIM BOARD	Scratched	580.00 FL	*321.00 FL
3	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*86.80 FL
4	1		*REAR TAILGATE HONDA EMBLEM	Necessary	81.30 FL	*81.30 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	84.00 FL	*84.00 FL
6	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*120.00 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Cut	155.00 FL	*155.00 FL
8	1		*REAR TAILGATE LOCK	Jammed	550.00 FL	*230.00 FL
9	1		*REAR TAILGATE LOCK CATCH	Serviceable	180.00 FL	*- FL
10	1		*REAR RH TAIL LAMP	Crumpled	780.00 FL	*530.00 FL
11	1		*REAR RH TAIL LAMP REFLECTOR	Scratched	480.00 FL	*480.00 FL
12	1		*REAR LH TAIL LAMP	Crumpled	780.00 FL	*530.00 FL
13	1		*REAR LH TAIL LAMP REFLECTOR	Scratched	480.00 FL	*480.00 FL
14	1		*REAR END PANEL	Dented	830.00 FL	*580.00 FL
15	1		*REAR END PANEL TOP GARNISH	Crumpled	155.00 FL	*155.00 FL
16	1		*REAR BUMPER	Crumpled	955.00 FL	*850.00 FL
17	1		*REAR BUMPER RH REFLECTOR	Serviceable	180.00 FL	*- FL
18	1		*REAR BUMPER LH REFLECTOR	Serviceable	180.00 FL	*- FL
19	1		*REAR SPARE TYRE TOOL BOX	Crumpled	480.00 FL	*380.00 FL
20	1		*REAR SPARE TYRE PANEL	Dented	2,000.00 FL	*1,050.00 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	180.00 FS	*30.00 FS
22	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*20.00 FS
23	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
24	1		*SET BODY SEALANT	Necessary	300.00 FS	*50.00 FS
25	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*40.00 FS
26	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,732.10	7,736.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,132.42	1,479.22
Total Parts (\$\$)	9,599.68	6,256.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE,REAR END PANEL,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS,ALSO INCLUDE CUTTING OUT AND WELDING OF REPLACEMENT SPARE TYRE PANEL,REPAIR FENDER	New	1,200.00	1,100.00
2	TO RESPRAY REAR TAILGATE,END PANEL AND SPARE TYRE PANEL	New	800.00	800.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	120.00
4	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	180.00	60.00
5	TOWING FEE (NPA)	New	0.00	0.00
6	TO CHECK WIRING SYSTEM	New	100.00	30.00
7	TO CONDUCT A STANDARD OF OPEARING PROCEDURES POST REPAIRS SCAN TEST AS A REQUIREMENTS UPON COMPLETION OF COLLISION REPAIRS }	New	300.00	300.00
8	TO DEACTIVATE AND ACTIVE HIGH VOLTAGE HYBRID BATTERY AS A SAFETY PRECAUTIONS }	New	300.00	0.00
Gross Labour Cost (\$\$)			3,040.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >