

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001688/KDA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SHD9318J **Insured Vehicle No :** GBJ5995U

Date of Loss: 21/01/2020 **Nature of Claim:** TP **Claim No:** 6053283349SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No: | SHD9318J | | |
| Make & Model: | TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) | Engine No: | 2ZR2C33860 |
| Reg. Date: | 27/06/2019 (Man. Year: 2018) | Chassis No: | JTDKB3FU903081920 |
| Colour: | Metallic Pearl White/Red | Odometer: | 80635 km |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|---------------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Sailun 9 mm | Rear Left Side: | Goodyear 6 mm |
| Front Right Side: | Sailun 9 mm | Rear Right Side: | Goodyear 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 9,663.27 | 681.75 | 8,981.52 | 92.94 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 14,720.00 | 340.00 | 14,380.00 | 97.69 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 24,383.27 | 1,021.75 | 23,361.52 | 95.81 |
| + GST 7.00/7.00% (\$\$) | 1,706.83 | 71.52 | 1,635.31 | 95.81 |
| Nett Amount (\$\$) | 26,090.10 | 1,093.27 | 24,996.83 | 95.81 |
| + Loss of Use (1.5 x S\$50.00/day) (\$\$) | | 75.00 | | |
| + Car Rental (1.5 x S\$113.40/day) (\$\$) | | 170.10 | | |
| + Doc/Search Fee (\$\$) | | 7.49 | | |
| Nett Liability (\$\$) | | 1,345.86 | | |

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 30/01/2020 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|-------------|------------|
| 1 | 1 | | *REAR BUMPER | Repair | 442.60 FL | *- FL |
| 2 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 332.70 FL | *332.70 FL |
| 3 | 1 | | *REAR BUMPER TOWING COVER | Serviceable | 15.40 FL | *- FL |
| 4 | 1 | | *GUARD ,REAR BUMPER ,CENTER | Dented / Cut | 576.30 FL | *576.30 FL |
| 5 | 1 | | *REAR BUMPER SIDE RETAINER LH | Serviceable | 116.50 FL | *- FL |
| 6 | 1 | | *REAR BUMPER SIDE RETAINER RH | Serviceable | 117.70 FL | *- FL |
| 7 | 1 | | *REAR TAILGATE | Repair | 1,147.80 FL | *- FL |
| 8 | 1 | | *REAR TAILGATE OUTER GARNISH | Serviceable | 925.60 FL | *- FL |
| 9 | 1 | | *REAR TAILGATE WEATHERSTRIP | Serviceable | 372.30 FL | *- FL |
| 10 | 1 | | *PANEL SUB-ASSY ,BODY LOWER LOCK | Serviceable | 650.30 FL | *- FL |
| 11 | 1 | | *TAILLAMP LOWER RH | Serviceable | 502.00 FL | *- FL |
| 12 | 1 | | *TAILLAMP UPPER RH | Serviceable | 451.80 FL | *- FL |
| 13 | 1 | | *REAR BUMPER SIDE RH | Serviceable | 123.70 FL | *- FL |
| 14 | 1 | | *REAR BUMPER SIDE LH | Serviceable | 123.70 FL | *- FL |
| 15 | 1 | | *TAILLAMP LOWER LH | Serviceable | 502.00 FL | *- FL |
| 16 | 1 | | *TAILLAMP UPPER LH | Serviceable | 443.30 FL | *- FL |
| 17 | 1 | | *COVER ,DECK TRIM ,REAR | Serviceable | 126.70 FL | *- FL |
| 18 | 1 | | *COVER ,FLOOR UNDER ,NO 1 | Serviceable | 175.10 FL | *- FL |
| 19 | 1 | | *COVER ,FLOOR UNDER ,NO 2 | Serviceable | 241.90 FL | *- FL |
| 20 | 1 | | *COVER ,REAR FLOOR | Serviceable | 229.90 FL | *- FL |
| 21 | 1 | | *SET PARKING AID | Serviceable | 700.00 FS | *- FS |
| 22 | 1 | | *SET REAR BUMPER CLIP | Not Necessary | 66.00 FS | *- FS |
| 23 | 2 | | *REAR WINDSCREEN SEALANT | Not Necessary | 80.00 FS | *- FS |
| 24 | 1 | | *WINDSCREEN MOULDING | Not Necessary | 100.00 FS | *- FS |
| 25 | 1 | | *REAR WINDSCREEN INNER SPONGE SEAL | Not Necessary | 100.00 FS | *- FS |
| 26 | 1 | | *REAR TAILGATE TOYOTA LOGO | Not Necessary | 47.00 FS | *- FS |
| 27 | 1 | | *REAR TAILGATE WORDING PRIUS | Not Necessary | 52.90 FS | *- FS |
| 28 | 1 | | *REAR TAILGATE WORDING HYBRID | Not Necessary | 53.50 FS | *- FS |
| 29 | 1 | | *REAR TAILGATE STICKER TRANS-CAB | Not Necessary | 80.00 FS | *- FS |
| 30 | 1 | | *REAR TAILGATE STICKER 6555-3333 | Not Necessary | 80.00 FS | *- FS |
| 31 | 1 | | *REAR BUMPER PROTECTOR | Serviceable | 100.00 FS | *- FS |
| 32 | 1 | | *REAR WHEEL RIM | Serviceable | 1,879.40 FS | *- FS |
| 33 | 1 | | *REAR TYRE 195/65/15 | Serviceable | 350.00 FS | *- FS |
| 34 | 1 | | *REAR WHEEL RIM COVER | Serviceable | 211.50 FS | *- FS |
| 35 | 1 | | *REAR RH BUMPER RETAINER CLIP | Not Necessary | 25.00 FS | *- FS |
| 36 | 1 | | *REAR LH BUMPER RETAINER CLIP | Not Necessary | 25.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|---------------|
| Sub Total (\$) | 11,567.60 | 909.00 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 1,904.33 | 227.25 |
| Total Parts (\$) | 9,663.27 | 681.75 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|------------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 2 | TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 3 | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 4 | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR | New | 170.00 | 0.00 |
| 5 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 6,000.00 | 220.00 |
| 6 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | - |
| 7 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 0.00 |
| 8 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 0.00 |
| 9 | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 10 | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 11 | LABOUR CHARGE TO MOUNT AND VEHICLE ON JIG BENCH, TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 12 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 0.00 |
| 13 | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME | New | 6,000.00 | 120.00 |
| 14 | TO SUPPLY AND RE-DO REAR END PANEL INSULATION PADDING | New | 380.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 14,720.00 | 340.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >