

22/03/2002

ASS. REC. BY:

REF: C1/AG120001689/Pg

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Justin Wong

of

AG1

Date/Time:

23/01/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 8169T

Insured:

at Workshop m/s

Tel:

of

Policy No:

Claim No:

C10005375

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction

() Estimate

8500f

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg



Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Justin Wong
Sent: Thursday, 23 January 2020 10:11 AM
To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'assignments' <assignments@lkkauto.com>; Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Subject: Assignment to LKK for Damage Technical Report for SJK8169T || Our Ref: C10005325
Importance: High

Dear Bryan,

We require your assistance to prepare a damage technical report for our insured vehicle no: SJK8169T.

Kindly note that during the initial survey conducted by our surveyor, he discovered that both the front tyres badly worn out. LH front tyre has its wires and inner layer exposed, our surveyor initial assess was that these worn out tires will greatly reduce the braking efficiency and would be contributing factor to the accident as most of the braking force comes from the front wheels.

Please comment in your report on the efficiency and the condition the tires on whether these is one of the main contributory factors that can lead to the accident.

Our insured vehicle is currently at SME Motor Pte Ltd (Kaki Bukit).

Thank you.

A handwritten signature in black ink, appearing to be "JOK" followed by a large, stylized flourish or arrow pointing upwards and to the right.