

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001692/EEA3Q2

Date: 16/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100427585

Claimant
Vehicle No : SHC4474D **Insured Vehicle No :** SKV1669T

Date of Loss: 25/01/2020 Nature of Claim: TP Claim No: 9575613907SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4474D	Engine No:	2ZR6082382
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U405746928
Reg. Date:	09/07/2014 (Man. Year: 2014)	Odometer:	573300 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Achilles 5 mm	Rear Left Side:	Achilles 5 mm
Front Right Side:	Achilles 5 mm	Rear Right Side:	Achilles 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,731.90	2,197.92	8,533.98	79.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,506.00	1,180.00	2,326.00	66.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,237.90	3,377.92	10,859.98	76.28
Approved Total (Overridden) (S\$)		2,950.00		
Nett Amount (S\$)	14,237.90	2,950.00	11,287.90	79.28
+ Car Rental (9.0 x S\$133.75/day) (S\$)		1,203.75		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,160.75		
Global Sum Settlement (S\$)		4,160.00		

INSPECTION

Date of Assignment: 29/01/2020

Date Inspected: 29/01/2020 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER CLIPS (DISC 25%) (DISC 25%)	Necessary	16.10 F	*12.08 F
2	1	*TAIL GATE DOOR GLASS MOULDING RH (DISC 25%)	Necessary	29.40 F	*22.05 F
3	1	*TAIL GATE DOOR GLASS MOULDING LH (DISC 25%)	Necessary	29.40 F	*22.05 F
4	1	*MOULDING BACK WINDOW LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
5	1	*BUMPER REAR (DISC 25%)	Dented	458.60 F	*343.95 F
6	1	*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
7	1	*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Broken	94.80 F	*71.10 F
8	1	*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
9	1	*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
10	1	*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
11	1	*ARM SUB-ASSY ,RR BUMPER ,LH (DISC 25%)	Bent	139.60 F	*104.70 F
12	2	*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
13	1	*SENSOR REVERSE (SN)	Necessary	180.00 F	*180.00 F
14	1	*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
15	3	*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
16	1	*NUMBER PLATE (SN)	Bent	15.00 F	*15.00 F
17	1	*NUMBER PLATE FRAME (SN)	Necessary	12.00 F	*12.00 F
18	1	*ANTENNA ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
19	1	*UNDER COVER SUB-ASSY RR FLOOR	Not Necessary	514.50 F	*- F
20	1	*END PANEL COVER ,DECK TRIM HOLE	Not Necessary	46.10 F	*- F
21	1	*SOLAR FILM	Not Necessary	700.00 F	*- F
22	1	*END PANEL COVER ,DECK TRIM RR	Not Necessary	121.10 F	*- F
23	1	*TAILGATE DOOR GLASS	Not Necessary	1,090.90 F	*- F
24	1	*TAILGATE LOWER WINDOW GLASS	Not Necessary	721.30 F	*- F
25	1	*TAILGATE LOCK COVER	Not Necessary	15.70 F	*- F
26	1	*STRIKER BACK DOOR	Not Necessary	48.90 F	*- F
27	1	*STICKER DECAL SMRT	Not Necessary	7.80 F	*- F
28	1	*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
29	1	*TAIL LAMP LH	Not Necessary	548.40 F	*- F
30	1	*TAIL LAMP BRACKET LH	Not Necessary	30.70 F	*- F
31	1	*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
32	1	*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*- F
33	1	*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
34	1	*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
35	1	*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
36	1	*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
37	1	*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
38	1	*TAILGATE DOOR WEATHER STRIP	Not Necessary	353.40 F	*- F
39	1	*TAILGATE OUTSIDE GARNISH	Not Necessary	504.90 F	*- F
40	1	*EMBLEM REAR	Not Necessary	60.30 F	*- F
41	1	*NAME PLATE (TOYOTA)	Not Necessary	51.90 F	*- F
42	1	*SPOILER REAR	Not Necessary	953.70 F	*- F
43	1	*NAME PLATE (PRIUS)	Not Necessary	60.80 F	*- F
44	1	*END PANEL	Repair	602.10 F	*- F
45	1	*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
F=Franchise part.					
				Total Parts (\$\$)	10,731.90 2,197.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,014.00	450.00
2	SPRAY PAINT	New	1,476.00	500.00
3	TOWING CHARGE	New	56.00	40.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
6	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	120.00
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
8	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
9	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
10	TO REPLACE SUNDRY PARTS	New	100.00	20.00
11	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$)			3,506.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >