

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWER SINGAPORE 048583

INV No. AC2005053

INV Date 20/07/2020

Reference CC6/QBE20001694/Ada3n2

Code OBE

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SMM 7338H

Insured Veh. GBA 2161B

Claim No. VC013429

Policy No. 8-V0008490-MVA-R005

Accident Date 28/01/2020

Inspection Date 30/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile					
QBE	E INSURANCE (SINGAPORE) PTE LTD Ref : CC6/QBE20001694/Ada3n2					
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date: 20-07-2020 Code: QBE				
1.		Policy Particulars	:- THIRD PARTY CLAIM			
	Insured Veh.	GBA 2161B	Veh. Inspected	SMM 7338H		
	Policy No.	8-V0008490-MVA-R005	Coverage (\$)	0.00		
	Claim No.	VC013429	Excess (\$)	0.00		
	Assign From		Assign Date	30/01/2020		
2.		Vehicle Partic	culars & Condition			
	Make & Model	TOYOTA NOAH	TA NOAH C.C 1797			
	Engine No.	HIDDEN	Year of Reg.	2019		
	Chassis No.	ZWR800389620	Colour	WHITE		
	Odometer	5729	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm		
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm		
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm		
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm		
4.	,	Description	on of Damages			
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.			
	DAMAGES SEE DI	ETAILS.				
5.		General	Information			
	Accident Date	28/01/2020	Inspection Date	30/01/2020		
	Survey held at	MG SOLUTION PTE LTD				
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	<b>5b.</b> Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 7338H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	DENTED	2,080.50	1,712.00
1	TAILGATE LOGO	NECESSARY	85.00	85.00
1	TAILGATE EMBLEM 'HYBRID SYNERGY DRIVE'	NECESSARY	82.50	82.50
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	330.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	190.00	190.00
1	REAR BUMPER	DEFORMED	691.30	691.30
2	REAR BUMPER SIDE RETAINER @\$80.00	NECESSARY	160.00	160.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	666.50	-
1	REAR END PANEL TOP GARNISH	DEFORMED	288.90	288.90
2	REVERSE SENSOR @\$360.00	DAMAGED (2 PCS ONLY)	720.00	520.00
1	TAILGATE ALTERNATIVE	CRACKED	115.00	115.00
1	TAILGATE BUZZLE	CRACKED	95.00	95.00
	LESS 25% DISCOUNT		-1,376.18	-984.93
			4,128.52	2,954.77
	SPECIAL NETT ITEMS			
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	TAILGATE WIDSCREEN INNER SEAL (SN)	NECESSARY	120.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	25.00	25.00
1	SET REAR END PANEL GARNISH CLIP (SN)	NECESSARY	25.00	10.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
			390.00	115.00
	<u>LABOUR</u>			
	TO PANEL BEAT,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,200.00	600.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	600.00
	TO TRANSFER TAIL GATE MECHANISM.		250.00	80.00
	LABOUR TO REMOVE AND REFIT WINDSCREEN .		120.00	120.00
	TUFF COAT.		180.00	60.00

Report Ref No. CC6/QBE20001694/Ada3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	250.00	-
	WIRING CHECK .		150.00	30.00
	REMOVE AND REFIX REVERSE CAMERA AN DISTANCE SETTING.		120.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	60.00
			3,590.00	1,610.00
	GRAND TOTAL		8,108.52	4,679.77

RECOMMENDED COST OF LUMP SUM REPAIRS		3,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/QBE20001694/Ada3n2



**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SMM 7338H

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SMM 7338H

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

