

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20001698/UBS3Q2

**Date:** 13/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100460171

**Claimant**  
**Vehicle No :** SKH7519C **Insured Vehicle No :** SGH1788D

Date of Loss: 20/01/2020 Nature of Claim: TP Claim No: 7185324714SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKH7519C</b>		
Make & Model:	SUZUKI SWIFT, 1.6 MT (M)	Engine No:	M16A1553369
Reg. Date:	26/05/2011 (Man. Year: 2010)	Chassis No:	JSAEJC31S00206258
Colour:	Yellow	Odometer:	196496 km
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	40.00	40.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	280.00	220.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>540.00</b>	<b>320.00</b>	<b>220.00</b>	<b>40.74</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	37.80	22.40	15.40	40.74
<b>Nett Amount (\$\$)</b>	<b>577.80</b>	<b>342.40</b>	<b>235.40</b>	<b>40.74</b>
<b>+ Loss of Use (2.0 x S\$60.00/day) (\$\$)</b>		120.00		
<b>Nett Liability (\$\$)</b>		<b>462.40</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>450.00</b>		

### INSPECTION

Date of Assignment: 28/05/2020

Date Inspected: 28/05/2020 Inspected At:

Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE	Scratched	40.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett.
<b>Total Parts (S\$)</b>					<b>40.00</b>	<b>40.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	200.00	80.00
2	SPRAY PAINTING	New	300.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>500.00</b>	<b>280.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**