

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001712/QEA3Q2

Date: 06/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900001627

Claimant
Vehicle No : SLF5864S **Insured Vehicle No :** SMG3322K

Date of Loss: 14/01/2020 Nature of Claim: TP Claim No: 6252436725SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF5864S	Engine No:	CGG333817
Make & Model:	VOLKSWAGEN POLO, 1.4 AT 6R13E7 (A)	Chassis No:	WVWZZZ6RZAU042078
Reg. Date:	31/05/2010 (Man. Year: 2010)	Odometer:	228498 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,600.00	2,340.00	260.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	1,440.00	3,020.00	67.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,060.00	3,780.00	3,280.00	46.46
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	7,060.00	3,000.00	4,060.00	57.51
+ Car Rental (5.0 x S\$60.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,307.45		

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 30/01/2020 Inspected At:

Fdk Automobile & Leasing Services
Pte Ltd (HQ)
39 WOODLANDS CLOSE MEGA @
WOODLANDS, #05-12
Singapore 737856

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT DOOR ASSY	Dented	1,200.00 F	*1,200.00 FL
2	1		*RIGHT REAR DOOR ASSY	Dented	1,400.00 F	*1,400.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,600.00	2,600.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	260.00
Total Parts (\$)	2,600.00	2,340.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REAR BUMPER +RIGHT SIDE FENDER PANEL BEATING	New	440.00	100.00
2	WIRING CHECKING LABOUR	New	120.00	40.00
3	SPRAY PAINTING (2 DOOR+REAR BUMPER+SIDE STEP +FENDER)	New	1,600.00	800.00
4	VOLKSWAGEN RIM REPAIR +SPRAY PAINTING	New	320.00	50.00
5	DOOR FITTING LABOUR (2 UNIT)+SHIFT PANEL +REAR BUMPER	New	1,980.00	450.00
Gross Labour Cost (S\$)			4,460.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >