

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001713/EPA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0001494
Claimant Vehicle No :	SLM8476Y	Insured Vehicle No :	SLX2826C
Date of Loss:	23/01/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0000254

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM8476Y	Engine No:	L15B4412391
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11212391
Reg. Date:	13/04/2017 (Man. Year: 2016)	Odometer:	73735 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,461.80	1,458.00	3,003.80	67.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,180.00	2,090.00	63.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,731.80	2,638.00	5,093.80	65.88
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	7,731.80	2,100.00	5,631.80	72.84
+ GST 7.00/7.00% (S\$)	541.23	147.00	394.23	72.84
Nett Amount (S\$)	8,273.03	2,247.00	6,026.03	72.84
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,749.00		

INSPECTION

Date of Assignment: 28/01/2020

Date Inspected: 29/01/2020 Inspected At:

Wah Hong Motors & Credit Pte Ltd
(HQ)
38 Toh Guan Road East, #01-57,
Enterprise Hub
Singapore 608581

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM8476Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	420.00 FL	*420.00 FL
2	1		*REAR BUMPER REFLECTOR LH	Not Necessary	65.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	65.00 FL	*- FL
4	1		*REAR CORNER PANEL LH	Not Necessary	190.00 FL	*- FL
5	1		*REAR CORNER PANEL RH	Not Necessary	190.00 FL	*- FL
6	1		*TAILGATE	Dented	850.00 FL	*850.00 FL
7	1		*TAILGATE GARNISH	Not Necessary	190.00 FL	*- FL
8	1		*TAILGATE LOCK ASSY	Bent	120.00 FL	*120.00 FL
9	1		*REAR LOCK STRICKER	Not Necessary	85.00 FL	*- FL
10	1		*TAILGATE LAMP LH	Not Necessary	380.00 FL	*- FL
11	1		*TAILGATE LAMP RH	Not Necessary	380.00 FL	*- FL
12	1		*REAR FENDER LAMP LH	Not Necessary	480.00 FL	*- FL
13	1		*REAR FENDER LAMP RH	Not Necessary	480.00 FL	*- FL
14	1		*TAILGATE INNER TRIM BOARD	Not Necessary	230.00 FL	*- FL
15	1		*END PANEL	Repair	470.00 FL	*- FL
16	1		*END PANEL TOP COVER	Not Necessary	100.00 FL	*- FL
17	1		*TAILGATE WEATHER STRIP	Not Necessary	180.00 FL	*- FL
18	1		*REAR WINDSCREEN CENTER SEAL	Necessary	55.00 FL	*55.00 FL
19	1		*REAR WINDSCREEN SEAL LH	Not Necessary	28.00 FL	*- FL
20	1		*REAR WINDSCREEN SEAL RH	Not Necessary	28.00 FL	*- FL
21	1		*VEZEL EMBLEM	Necessary	90.00 FL	*90.00 FL
22	1		*HONDA BADGE EMBLEM	Not Necessary	120.00 FL	*- FL
23	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
24	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
25	1		*REAR LICENSE PLATE WITH HOLDER	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,501.00	1,765.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,039.20	307.00
Total Parts (S\$)	4,461.80	1,458.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,600.00	600.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,200.00	400.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS	New	120.00	30.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREA	New	150.00	30.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	200.00	120.00
Gross Labour Cost (\$\$)			3,270.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >