

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001714/DEA3N2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900097836
Claimant
Vehicle No : SH6224P **Insured Vehicle No :** SMM8168A
Date of Loss: 26/01/2020 **Nature of Claim:** TP **Claim No:** 8547334385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH6224P**
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS066073
 Reg. Date: 03/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403564974
 Colour: Blue Odometer: 335040 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 5 mm Rear Left Side: Davanti 5 mm
 Front Right Side: Davanti 5 mm Rear Right Side: Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,987.92	6,993.37	9,994.55	58.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,910.00	730.00	2,180.00	74.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,897.92	7,723.37	12,174.55	61.19
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	19,897.92	6,150.00	13,747.92	69.09
+ GST 7.00/7.00% (S\$)	1,392.85	430.50	962.35	69.09
Nett Amount (S\$)	21,290.77	6,580.50	14,710.27	69.09
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
+ Car Rental (8.0 x S\$125.40/day) (S\$)		1,003.20		
Nett Liability (S\$)		7,983.70		

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 30/01/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
 Blk 9 Sector C, #01-42 Sin Ming
 Industrial Estate
 Singapore 575644

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Mtg Cracked	438.00 FL	*438.00 FL
2	1		*RADIATOR GRILLE EMBLEM	Not Necessary	88.00 FL	*- FL
3	1		*FRONT BUMPER COVER	Distorted / Mtg Broken	499.90 FL	*499.90 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	696.40 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Not Necessary	115.70 FL	*- FL
6	1		*FRONT BUMPER LOWER REINFORCEMENT BRACKET	Not Necessary	330.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	78.80 FL	*- FL
8	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	301.90 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Cracked	148.60 FL	*148.60 FL
10	1		*LAMP ASSY ,FOG, RH	Mtg Broken	920.00 FL	*920.00 FL
11	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	77.00 FL	*- FL
13	1		*SUPPORT FR BUMPER ,RH	Not Necessary	81.70 FL	*- FL
14	1		*BRACKET ,FRONT BUMPER SIDE ,RH	Not Necessary	82.30 FL	*- FL
15	1		*BRACKET ,FRONT BUMPER SIDE ,LH	Not Necessary	82.30 FL	*- FL
16	1		*BRACKET ,FRONT BUMPER MOUNTING	Not Necessary	29.60 FL	*- FL
17	1		*BRACKET ,FRONT BUMPER MOUNTING, NO.2	Not Necessary	97.80 FL	*- FL
18	1		*UNIT ASSY ,HEADLAMP RH (LED)	Scratched / Mtg Broken	3,455.00 FL	*3,455.00 FL
19	1		*UNIT ASSY ,HEADLAMP RH (LED)	Mtg Broken	3,455.00 FL	*3,455.00 FL
20	1		*HEAD LAMP PANEL (RH)	Bent	240.10 FL	*240.10 FL
21	1		*TOP PANEL CENTRE	Not Necessary	364.98 FL	*- FL
22	1		*TOP PANEL SIDE O/S	Bent	145.90 FL	*145.90 FL
23	1		*BRACKET ,HEADLAMP MOUNTING ,RH	Not Necessary	25.50 FL	*- FL
24	1		*BRACKET ,HEADLAMP MOUNTING ,LH	Not Necessary	25.50 FL	*- FL
25	1		*FRONT FENDER SHIELD	Not Necessary	198.50 FL	*- FL
26	1		*FRONT FENDER SHIELD CLIP	Not Necessary	14.90 FL	*- FL
27	1		*FRONT FENDER HYBRID EMBLEM ,RH	Not Necessary	86.50 FL	*- FL
28	1		*BRACKET ,FRONT SIDE PANEL ,RH	Not Necessary	44.50 FL	*- FL
29	1		*EXTENSION ,FRONT FENDER ,RH	Not Necessary	47.20 FL	*- FL
30	1		*WIPER SPARE TANK	Not Necessary	183.75 FL	*- FL
31	1		*WIPER SPARE TANK MOTOR	Not Necessary	242.70 FL	*- FL
32	1		*WIPER SPARE TANK FLOAT (NECK)	Not Necessary	55.50 FL	*- FL
33	1		*WIRING FRONT	Not Necessary	8,450.50 FL	*- FL
34	1		*FRONT BUMPER LOGO	Not Necessary	87.10 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,213.13 9,324.50
- List Item Discount on L Items 20.00/25.00% (\$\$) 4,225.21 2,331.13

Total Parts (\$\$) 16,987.92 6,993.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	400.00
2	SPRAY PAINTING CHARGE	New	1,000.00	300.00
3	WIRING CHARGE	New	120.00	30.00
4	TUFF KOTE	New	120.00	0.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX RADIATOR	New	90.00	0.00
7	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
8	REMOVE /REFIX FUSE BOX	New	180.00	0.00
Gross Labour Cost (\$\$)			2,910.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >