

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001741/KKA3Q2

Date: 11/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800073726

Claimant
Vehicle No : SKH760S **Insured Vehicle No :** SMA5934M

Date of Loss: 21/01/2020 Nature of Claim: TP Claim No: 7970420008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH760S**

Make & Model: MERCEDES-BENZ C180 BLUE EFFICIENCY, 1.6 (A) Engine No: 27491030014423

Reg. Date: 01/11/2012 (Man. Year: 2012) Chassis No: WDD2040312A772605

Colour: Metallic Dark Grey Odometer: 126274 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,251.00	1,285.20	965.80	42.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	800.00	300.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,351.00	2,085.20	1,265.80	37.77
Approved Total (Overridden) (S\$)		1,650.00		
Nett Amount (S\$)	3,351.00	1,650.00	1,701.00	50.76
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		1,830.00		

INSPECTION

Date of Assignment: 31/01/2020

Date Inspected: 31/01/2020 Inspected At: Jin Huat & Co (HQ)
176 SIN MING DRIVE #05-01, SIN
MING AUTOCARE
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,238.00 F	*1,238.00 FL
2	1		*REAR LEFT T/LAMP	Not Necessary	635.00 F	*- FL
3	1		*REAR BUMPER MOULDING	Cracked	145.00 F	*145.00 FL
4	1		*REAR BUMPER SENSOR	Not Necessary	188.00 F	*- FL
5	1		*REAR BUMPER RETAINER	Distorted	45.00 F	*45.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,251.00	1,428.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	142.80

Total Parts (\$\$)	2,251.00	1,285.20
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR & REPLACE PARTS	New	500.00	350.00
2	SPRAY PAINTING	New	600.00	450.00
Gross Labour Cost (\$)			1,100.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >