Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/AIG20001742/KEA3Q2 Our File No:

Date: 30/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100269881-08 Claimant

Insured Vehicle No: SKC4100Y SJG574E Vehicle No:

TP Date of Loss: 22/01/2020 Nature of Claim: Claim No: 8969634050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJG574E Reg No:

Make & Model: TOYOTA PREMIO, 1.5 F (A) Engine No: 1NZD099327 Reg. Date: 19/06/2008 (Man. Year: 2008) Chassis No: NZT2603028643 Colour: Metallic Maroon Odometer: 287938 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15 Rear Left Side: CST 7 mm Front Left Side: MAXIMUM 9 mm Front Right Side: Rear Right Side: CST 7 mm MAXIMUM 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,710.96	2,164.36	3,546.60	62.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,375.00	1,045.00	1,330.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,085.96	3,209.36	4,876.60	60.31
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	8,085.96	2,550.00	5,535.96	68.46
+ GST 7.00/7.00% (S\$)	566.02	178.50	387.52	68.46
Nett Amount (S\$)	8,651.98	2,728.50	5,923.48	68.46
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Se	earch Fee (S\$)	7.45		
Net	t Liability (S\$)	3,235.95		

INSPECTION

Date of Assignment: 29/01/2020

Date Inspected: 03/02/2020 Inspected At: COMPLETE VMS PTE LTD (HQ)

176 Sin Ming Drive #03-14 Sin Ming

Autocare Complex Singapore 575721

4.0 days Estimated Period of Repair:

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BOOT LID	Repair	964.20 FL	*- FL	
2	1		*BOOT LID LOCK	Repair	371.30 FL	*- FL	
3	1		*PRIMO EMBLEM	Necessary	78.00 FL	*78.00 FL	
4	1		*EMBLEM R/H	Necessary	75.00 FL	*75.00 FL	
5	1		*TOYOTA LOGO	Necessary	67.20 FL	*67.20 FL	
6	2		*BOOT LID REFLECTOR	Serviceable	672.00 FL	*-FL	
7	1		*TAIL LAMP	N/S Mtg Cracked	966.00 FL	*415.00 FL	
8	2		*TAIL LAMP CLIP	Not Necessary	13.00 FL	*- FL	
9	1		*REAR END PANEL	Bent	644.20 FL	*508.20 FL	
10	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	281.00 FL	*233.85 FL	
11	1		*REAR BUMPER	Buckled / Cracked	855.00 FL	*855.00 FL	
12	1		*REAR BUMPER REINFORCEMENT	No such part	431.00 FL	*- FL	
13	1		*REAR BUMPER SPONGE	No such part	197.00 FL	*- FL	
14	6		*REAR BUMPER CLIP	Necessary	36.00 FL	*36.00 FL	
15	2		*REAR BUMPER BRACKET	Repair	184.40 FL	*- FL	
16	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	374.40 FL	*187.20 FL	
17	1		*BOOT WEATHERSTRIP	Serviceable	316.00 FL	*-FL	
18	1		*REAR END PANEL IMMOBILIZER SENSOR	Serviceable	263.00 FL	*- FL	
19	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS	
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.	,			
				Sub Total (S\$)	7,068.70	2,655.45	
	- List Item Discount on L Items 20.00/20.00% (S\$)				1,357.74	491.09	
				Total Parts (S\$)	5,710.96	2,164.36	
	Report was unsubmitted during this print-out						

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	RUST PROOFING TREATMENT	New	100.00	30.00
2	CHANGE TAIL LAMP AND CHECK WIRING	New	75.00	15.00
3	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,100.00	500.00
4	TO CUT OFF REAR END PANEL,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE NECESSARY PARTS	New ALL	1,100.00	500.00
	Gross Labour Cost (S\$)		2,375.00	1,045.00
	Report was unsubmitted of	during this print-out.		

< END OF ESTIMATES >