

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001743/BGA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993928

Claimant
Vehicle No : SJU4706S **Insured Vehicle No :** GBJ6778Z

Date of Loss: 28/01/2020 Nature of Claim: TP Claim No: 8806301427SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU4706S**

Make & Model: TOYOTA WISH, 1.8 X (A)

Engine No: 2ZR0418822

Reg. Date: 11/12/2009 (Man. Year: 2009)

Chassis No: ZGE200003330

Colour: White

Odometer: 297390 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,786.57	5,165.16	4,621.41	47.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	2,290.00	1,640.00	41.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,716.57	7,455.16	6,261.41	45.65
Approved Total (Overridden) (S\$)		5,950.00		
Nett Amount (S\$)	13,716.57	5,950.00	7,766.57	56.62
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
(S\$)		6,670.00		
Liabile Amount (50.00%) (S\$)		3,335.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,371.45		

INSPECTION

Date of Assignment: 28/01/2020

Date Inspected: 29/01/2020 Inspected At:

160 Sin Ming Drive #01-14

Repairer : Team Autopro Pte Ltd (Sin Ming)

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,120.00 FL	*- FL
2	1		*FRONT GRILLE	Broken	362.00 FL	*362.00 FL
3	1		*HEADLAMP LH	Missing	1,206.90 FL	*918.97 FL
4	1		*HEADLAMP BRACKET LH	Broken	154.00 FL	*85.00 FL
5	1		*FRONT BUMPER	Broken	1,096.00 FL	*545.10 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	268.00 FL	*123.80 FL
7	1		*FRONT BUMPER GRILLE	No such part	113.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	287.00 FL	*- FL
9	1		*FRONT BUMPER INNER SPONGE	Broken	182.00 FL	*108.50 FL
10	1		*FRONT SUPPORT PANEL	Bent	699.40 FL	*699.40 FL
11	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	327.50 FL	*182.00 FL
12	1		*AIR DUCT	Distorted	326.00 FL	*130.00 FL
13	1		*FRONT FOG LAMP COVER	Not Damaged	127.50 FL	*- FL
14	1		*FRONT FENDER LH	Dented	978.00 FL	*645.10 FL
15	1		*FRONT FENDER LAMP	Short Circuit	89.00 FL	*69.70 FL
16	1		*FRONT FENDER INNER SHIELD	Torn	216.00 FL	*155.20 FL
17	1		*FRONT SHOCK ABSORBER LH	Not Damaged	319.60 FL	*- FL
18	1		*FRONT LOWER ARM LH	Dented	394.50 FL	*394.50 FL
19	1		*FRONT KNUCKLE ARM LH	Not Damaged	365.80 FL	*- FL
20	1		*FRONT KNUCKLE ARM BEARING LH	Not Damaged	135.00 FL	*- FL
21	1		*FRONT WHEEL HUB WITH BEARING LH	Not Damaged	251.00 FL	*- FL
22	1		*SIDE MIRROR	Repair	356.00 FL	*- FL
23	1		*SIDE SKIRT	Dislodged	423.00 FL	*423.00 FL
24	1		*FRONT DOOR LH	Dented	1,292.30 FL	*1,292.30 FL
25	1		*FRONT DOOR BLACK TAPE LH	Necessary	92.60 FL	*45.64 FL
26	1		*NUMBER PLATE WITH GARNISH		80.00 FS	*50.00 FS
27	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*SIDESKIRT CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*HEADLAMP CLIPS	Necessary	60.00 FS	*30.00 FS
32	1		*FRONT ALLOY RIM - LH (LOCAL REPAIR)		650.00 FS	*300.00 FS
33	1		*FRONT TYRE LH	Not Damaged	350.00 FS	*- FS
34	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,582.10	6,710.21
- List Item Discount on L Items 25.00/25.00% (S\$)	2,795.53	1,545.05
Total Parts (S\$)	9,786.57	5,165.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT & REALIGN FRONT ACCIDENT DAMAGE PORTION	New	1,400.00	1,000.00
2	TO SPRAY FRONT ACCIDENT DAMAGE PORTION	New	1,400.00	1,000.00
3	R&R FRONT UNDER CARRIAGE	New	350.00	120.00
4	R&R WIPER GARNISH	New	120.00	0.00
5	WHEEL ALIGNMENT	New	180.00	60.00
6	TYRE ROTATION AND BALANCING	New	180.00	0.00
7	R&R WIRE HARNESS AND CHECK FUNCTION	New	150.00	50.00
8	RUST PROOFING	New	150.00	60.00
Gross Labour Cost (\$\$)			3,930.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >