

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001744/KEA3N2

Date: 22/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900165119

Claimant
Vehicle No : SJJ490Y **Insured Vehicle No :** SMQ3366G

Date of Loss: 25/01/2020 Nature of Claim: TP Claim No: 7831671902SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ490Y	Engine No:	1ZZ3128789
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W403000603
Reg. Date:	31/08/2008 (Man. Year: 2008)	Odometer:	210423 km
Colour:	Metallic Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,009.75	3,897.50	4,112.25	51.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,695.00	1,460.00	1,235.00	45.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,704.75	5,357.50	5,347.25	49.95
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	10,704.75	4,250.00	6,454.75	60.30
+ GST 7.00/7.00% (S\$)	749.33	297.50	451.83	60.30
Nett Amount (S\$)	11,454.08	4,547.50	6,906.58	60.30
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,394.95		

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 31/01/2020 Inspected At:

COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,560.00 FL	*1,210.40 FL
2	1		*TAIL GATE W/SCREEN MOULDING TOP	Necessary	89.00 FL	*89.00 FL
3	1		*TAIL GATE W/SCREEN MOULDING BOTTOM	Necessary	63.00 FL	*63.00 FL
4	2		*TAIL GATE W/SCREEN MOULDING SIDE	Necessary	158.40 FL	*158.40 FL
5	1		*TAIL GATE LOCK	Dented	471.60 FL	*397.80 FL
6	2		*TAIL GATE ABSORBER	Serviceable	423.40 FL	*- FL
7	1		*AERO TOURER EMBLEM	Necessary	68.20 FL	*68.20 FL
8	1		*BORNEO MOTOR EMBLEM	Necessary	77.30 FL	*77.30 FL
9	1		*TOYOTA LOGO	Necessary	90.00 FL	*90.00 FL
10	1		*TAIL GATE OUTER CHROME HANDLE	Serviceable	325.00 FL	*- FL
11	1		*TAIL GATE INNER TRIM	Mtg Cracked	616.00 FL	*444.30 FL
12	6		*TAIL GATE INNER TRIM CLIP	Necessary	33.00 FL	*33.00 FL
13	1		*TAIL GATE SPOILER	Serviceable	865.00 FL	*- FL
14	1		*TAIL GATE INNER HANDLE	Dented	61.70 FL	*61.70 FL
15	1		*TAIL GATE SURROUND RUBBER SEAL (50%)	Cut	243.75 FS	*162.50 FS
16	1		*REAR BUMPER	Buckled	1,247.10 FL	*515.00 FL
17	2		*REAR BUMPER BRACKET	Repair	144.00 FL	*- FL
18	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	157.80 FL	*78.90 FL
19	6		*REAR BUMPER CLIP	Necessary	76.80 FL	*76.80 FL
20	2		*REAR BUMPER LOWER REFLECTOR	Serviceable	78.00 FL	*- FL
21	1		*TAIL LAMP R/H	Mtg Cracked	491.60 FL	*408.00 FL
22	1		*REAR END PANEL	Bent	768.30 FL	*521.20 FL
23	1		*REAR END PANEL TOP GARNISH	Cut	311.80 FL	*285.00 FL
24	4		*REAR END PANEL TOP GARNISH CLIP	Necessary	22.00 FL	*22.00 FL
25	1		*SPARE TIRE PANEL TOP GARNISH	Serviceable	485.00 FL	*- FL
26	1		*TAIL GATE W/SCREEN SEALANT	Necessary	65.00 FS	*40.00 FS
27	1		*TAIL GATE NUMBER PLATE }	Dented	25.00 FS	*45.00 FS
28	1		*TAIL GATE NUMBER PLATE HOLDER }	Dented	33.00 FS	*- FS
29	1		*REVERSE CAMERA	Serviceable	850.00 FS	*- FS
30	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,180.75	5,047.50
- List Item Discount on L Items 25.00/25.00% (\$)	2,171.00	1,150.00
Total Parts (\$)	8,009.75	3,897.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REINSTALL REAR W/SCREEN GLASS	New	180.00	120.00
2	TRANSFER TAILGATE COMPONENT TO NEW GATE	New	150.00	60.00
3	RUST PROOFING TREATMENT	New	100.00	60.00
4	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,100.00	600.00
5	CHANGE TAIL LAMP AND CHECK LIGHTING	New	65.00	20.00
6	TO CUT OFF REAR END PANEL ,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	New	1,100.00	600.00
Gross Labour Cost (\$\$)			2,695.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >