

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20001745/T1PA3Q2**Date:** 14/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKF5824U	Insured Vehicle No :	SHC1041P
Date of Loss:	24/01/2020	Nature of Claim:	TP
		Claim No:	MCT20010578

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF5824U	Engine No:	HIDDEN
Make & Model:	HONDA CIVIC, 2.0 TYPE-R (M)	Chassis No:	FD21401080
Reg. Date:	01/03/2008 (Man. Year: 2008)	Odometer:	236252 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,169.87	3,094.04	11,075.83	78.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	730.00	2,470.00	77.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,369.87	3,824.04	13,545.83	77.98
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	17,369.87	3,000.00	14,369.87	82.73
+ GST 7.00/7.00% (S\$)	1,215.89	210.00	1,005.89	82.73
Nett Amount (S\$)	18,585.76	3,210.00	15,375.76	82.73
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	30/01/2020	
Date Inspected:	31/01/2020	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2021)
Parts:	144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF5824U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBLEM	Not Necessary	97.74 FL	*- FL
2	2		*FRONT EMBLEM RETAINER	Not Necessary	150.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	400.20 FL	*- FL
4	1		*FRONT SUPPORT PANEL	Not Necessary	626.75 FL	*- FL
5	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	110.40 FL	*- FL
6	1		*FRONT HEADLAMP LH	Not Necessary	1,030.35 FL	*- FL
7	1		*FRONT HEADLAMP RH	Cracked	1,030.35 FL	*914.80 FL
8	1		*FRONT HEADLAMP BRACKET	O/S Bent	80.50 FL	*40.25 FL
9	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	132.25 FL	*- FL
10	1		*FRONT BONNET LOCK	Not Necessary	119.20 FL	*- FL
11	1		*AIRCON CONDENSER	Not Necessary	876.30 FL	*- FL
12	1		*RADIATOR	Not Necessary	1,481.20 FL	*- FL
13	1		*RADIATOR COWLING	Not Necessary	120.75 FL	*- FL
14	1		*RADIATOR FAN MOTOR ASSY	Not Necessary	369.15 FL	*- FL
15	1		*RADIATOR EXPANSION TANK	Not Necessary	63.25 FL	*- FL
16	1		*WIPER WASHER TANK	Not Necessary	86.25 FL	*- FL
17	1		*FRONT BUMPER (AFTER MARKET)	Cracked	1,600.00 FS	*1,200.00 FS
18	1		*FRONT BUMPER LOWER MESH (AFTER MARKET)	Not Necessary	250.00 FS	*- FS
19	1		*FRONT BUMPER LOWER GARNISH (AFTER MARKET)	Not Necessary	800.00 FS	*- FS
20	1		*FRONT BUMPER SIDE GARNISH LH (AFTER MARKET)	Not Necessary	180.00 FS	*- FS
21	1		*FRONT BUMPER SIDE GARNISH RH (AFTER MARKET)	Not Necessary	180.00 FS	*- FS
22	1		*FRONT GRILLE (AFTER MARKET)	Not Necessary	410.00 FS	*- FS
23	1		*FRONT FENDER RH (AFTER MARKET)	Cracked	1,500.00 FS	*1,100.00 FS
24	1		*FRONT BONNET (AFTER MARKET)	Not Necessary	1,850.00 FS	*- FS
25	1		*OIL COOLER	Not Necessary	1,530.00 FS	*- FS
26	1		*OIL COOLER PIPR	Not Necessary	250.00 FS	*- FS
27	1		*FRONT NUMBER PLATE	Not Necessary	70.00 FS	*- FS
28	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
29	1		*SET FRONT GRILLE CLIP	Not Necessary	20.00 FS	*- FS
30	1		*SET FRONT FENDER INNER TRM CLIP	Not Necessary	20.00 FS	*- FS
31	1		*BOT COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,524.84	3,285.05
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,354.97	191.01
Total Parts (\$\$)	14,169.87	3,094.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,RENEW AIRCON CONDENSER AND TOP UP GAS	New	150.00	0.00
3	REMOVE ,RENEW RADIATOR AND TOP UP COOLANT	New	150.00	0.00
4	REMOVE AND RENEW OIL COOLER	New	120.00	0.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	400.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	300.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			3,200.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >