Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001746/KEA3Q2

35585 km

Date: 30/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900244760 Claimant SFE1330T Insured Vehicle No: SMQ3704P Vehicle No:

Date of Loss: ΤP 24/01/2020 Nature of Claim: Claim No: 4219038581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SFE1330T Reg No:

Make & Model: MERCEDES-BENZ GLC 250, 2.0 4MATIC (A) Engine No: 27492031155417 Reg. Date: 17/11/2017 (Man. Year: 2017) Chassis No: WDC2539462F307339

Colour: Odometer: Metallic Grey

Engine Capacity: 1991 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 6 mm Front Right Side: Rear Right Side: Pirelli 6 mm Pirelli 7 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
1,289.52	1,208.52	81.00	6.28
0.00	0.00	0.00	
1,260.00	870.00	390.00	30.95
0.00	0.00	0.00	
0.00	0.00	0.00	
2,549.52	2,078.52	471.00	18.47
178.47	145.50	32.97	18.47
2,727.99	2,224.02	503.97	18.47
	1,289.52 0.00 1,260.00 0.00 0.00 2,549.52 178.47	1,289.52 1,208.52 0.00 0.00 1,260.00 870.00 0.00 0.00 0.00 0.00 2,549.52 2,078.52 178.47 145.50	1,289.52 1,208.52 81.00 0.00 0.00 0.00 1,260.00 870.00 390.00 0.00 0.00 0.00 0.00 0.00 0.00 2,549.52 2,078.52 471.00 178.47 145.50 32.97

+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$) 513.60 + Doc/Search Fee (S\$) 2.00

> **Nett Liability (S\$)** 2,739.62

INSPECTION

Date of Assignment: 13/03/2020

13/03/2020 Optima Werkz Pte Ltd (HQ) Date Inspected: Inspected At:

6 Kung Chong Road Singapore 159143

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR WHEEL ARCH EXTENTION COVER RH	Dented / Cut	240.00 FL	*240.00 FL	
2	1		*REAR ALLOY RIM RH	Dented	1,140.00 FL	*1,050.00 FL	
3	6		*REAR WHEEL ARCH EXTENTION COVER CLIPS RH	Necessary	52.80 FL	*52.80 FL	
4	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL	
5	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL	
6	1		*REAR QUARTER PANEL RH (NPA)	Repair	0.00 FL	*- FL	
F=Fra	ınchise	part. L=List	ItemDisc.				
			•	Sub Total (S\$)	1,432.80	1,342.80	
- List Item Discount on L Items 10.00/10.00% (S\$)					143.28	134.28	
			т	otal Parts (S\$)	1,289.52	1,208.52	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST ACCIDENT AREAS & ETC	New	400.00	300.00					
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH ,REAR BUMPER ,REAR QUARTER PANEL RH & ETC	New	700.00	480.00					
3	LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC	New	100.00	30.00					
4	TO WHEEL ALIGNMENT & BALANCING	New	60.00	60.00					
	Gross Labor	ur Cost (S\$)	1,260.00	870.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >