

ASS. REC. BY:

REF:

AG/20001746/Ken3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Size 1330T

Yr Regn:

11.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer CLK 250

c.c

1991

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

35585

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDC 25394621-307339

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

24/1/20

D.O.I.

13/3/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Date: 31.01.2020
 Vehicle No: SFE1330T
 Model: MERCEDEZ BENZX GLC250
 Chassis: WDC2539462F307339-2017
 Reg.Year: 2017

Third Party Insurer: AIG
 Third Party Veh No: SMQ3704P
 Date of Accident: 24.01.2020

*Not wither
 survey after paint
 4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR WHEEL ARCH EXTENTION COVER RH	1	<i>Not in</i>	\$240.00
2	REAR ALLOY RIM RH	1	<i>Not</i>	\$1,140.00
3	REAR WHEEL ARCH EXTENTION COVER CLIPS RH	6	\$8.80	\$52.80
4	REAR DOOR RH	1		REPAIR
5	REAR BUMPER	1		REPAIR
6	REAR QUARTER PANEL RH	1		REPAIR
SUB TOTAL				\$1,432.80
LESS 10%				-\$143.28
PARTS TOTAL				\$1,289.52

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST ACCIDENT AREAS & ETC. \$400.00 *300*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR BUMPER, REAR QUARTER PANEL RH & ETC. \$700.00 *480*

LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC. \$100.00 *30*

TO WHEEL ALIGNMENT & BALANCING. \$60.00 ✓

LABOUR TOTAL \$1,260.00

ONG TOTAL \$2,549.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

