

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20001748/APS3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010890-01

Claimant
Vehicle No : SLF9285L **Insured Vehicle No :** SKE3774Z

Date of Loss: 20/01/2020 **Nature of Claim:** TP **Claim No:** 1202000003504

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF9285L	Engine No:	G4NAGH847434
Make & Model:	KIA SPORTAGE, 2.0 (A)	Chassis No:	KNAPN81AMG7042702
Reg. Date:	16/09/2016 (Man. Year: 2016)	Odometer:	59021 km
Colour:	Red		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,730.86	2,297.01	433.85	15.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	430.00	1,140.00	72.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,300.86	2,727.01	1,573.85	36.59
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	4,300.86	2,150.00	2,150.86	50.01
+ GST 7.00/7.00% (S\$)	301.06	150.50	150.56	50.01
Nett Amount (S\$)	4,601.92	2,300.50	2,301.42	50.01
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,607.95		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 04/02/2020 Inspected At:

Twincar Automotive Pte Ltd - Kaki Bukit (HQ)
2 KAKI BUKIT AVENUE 2, #01-17
KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
Parts:	M1-SUV	KIA SPORTAGE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF9285L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	638.00 FL	*638.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	68.00 FL	*- FL
3	1		*FRONT BUMPER LOWER LID	Cut	357.00 FL	*357.00 FL
4	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Cracked	45.00 FL	*22.50 FL
5	1		*FRONT LH BUMPER FOGLAMP	Not Necessary	336.00 FL	*- FL
6	1		*FRONT LH BUMPER FOGLAMP GARNISH	Cracked	185.00 FL	*185.00 FL
7	1		*FRONT LH BUMPER SIDE AIR DUCT	Deformed	39.00 FL	*39.00 FL
8	1		*FRONT LH BUMPER SIDE AIR DUCT GARNISH	Deformed	48.00 FL	*48.00 FL
9	1		*FRONT LH HEADLAMP	Cut	1,201.00 FL	*1,201.00 FL
10	1		*FRONT LH HEADLAMP LOWER BRACKET	Cracked	28.40 FL	*28.40 FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,025.40	2,548.90
- List Item Discount on L Items 10.00/10.00% (S\$)	294.54	251.89
Total Parts (S\$)	2,730.86	2,297.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR)	New	100.00	30.00
2	TO RESET SYSTEM AFTER REPAIR WORKS	New	250.00	0.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	200.00
4	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	200.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	0.00
Gross Labour Cost (\$\$)			1,570.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >