

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20001753/T1BS3Q2

Date: 04/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900253010

Claimant
Vehicle No : SML9181J **Insured Vehicle No :** SMQ7574X

Date of Loss: 24/01/2020 Nature of Claim: TP Claim No: 0961650066SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML9181J**
 Make & Model: SKODA OCTAVIA, 1.4 AMBITION PLUS TSI (A) Engine No: DLB029674
 Reg. Date: 25/04/2019 (Man. Year: 2018) Chassis No: TMBBU7NE4K0114466
 Colour: Grey Odometer: 0 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,809.77	6,182.07	627.70	9.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	7,940.00	4,980.00	38.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,729.77	14,122.07	5,607.70	28.42
+ GST 7.00/7.00% (S\$)	1,381.08	988.54	392.54	28.42
Nett Amount (S\$)	21,110.85	15,110.61	6,000.24	28.42
+ Car Rental (12.0 x S\$120.00/day + 7.00% GST) (S\$)		1,540.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,653.41		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 04/02/2020 Inspected At: Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR (REAR BUMPER COVER)	Deformed	1,375.00 FS	*1,375.00 FS
2	1		*CONNECTING BUMPER UPPER SIDE TRIM LH	Necessary	28.20 FS	*28.20 FS
3	1		*GUIDE PIEC (BUMPER GUIDE LH)	Necessary	20.30 FS	*20.30 FS
4	1		*WHEELHOUSE	Cut	107.00 FS	*107.00 FS
5	6		*EXPANDING NUT	Necessary	4.86 FS	*4.86 FS
6	1		*SPOILER	Not Necessary	177.00 FS	*- FS
7	1		*SENSOR BRA	Necessary	11.40 FS	*11.40 FS
8	2		*SENSOR BRA	Necessary	22.80 FS	*22.80 FS
9	1		*SENSOR BRA	Necessary	11.40 FS	*11.40 FS
10	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
11	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
12	1		*COVER LH TAILLAMP SIDE COVER (BLACK)	Necessary	20.90 FS	*20.90 FS
13	1		*TAILLIGHT (LH TAILLIGHT)	Cracked	685.00 FS	*685.00 FS
14	2		*UNBEKANNT TAILLIGHT PLUG	Necessary	2.32 FS	*2.32 FS
15	1		*SECTIONAL (LHR FENDER)	Buckled	1,130.00 FS	*1,130.00 FS
16	1		*FOIL REAR FENDER FOIL LH	Necessary	51.95 FS	*51.95 FS
17	1		*INSERT PLA TAILLIGHT PANEL LH	Not Necessary	251.00 FS	*- FS
18	1		*VENT TRIM LHS RR FENDER AIR DUCT	Not Necessary	55.70 FS	*- FS
19	1		*INOX-SPRAY	Necessary	62.88 FS	*62.88 FS
20	1		*SEALANT CAN BE SPRAYED	Necessary	61.67 FS	*61.67 FS
21	1		*2K-BODY ADHESIVE	Necessary	406.76 FS	*406.76 FS
22	1		*RUBBER VALVE	Necessary	3.29 FS	*3.29 FS
23	1		*ALLOY WHEE	Cut	1,465.00 FS	*1,465.00 FS
24	1		*TYRE (80 %)	Cut	720.00 FS	*576.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,809.77** **6,182.07**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	WHEEL ALIGNMENT	New	360.00	360.00
4	R&R RIM & BALANCE	New	50.00	50.00
5	CHECK WATERLEAK TEST	New	150.00	150.00
6	R&R LUGGAGE COMPARTMENT TRIM	New	840.00	420.00
7	LABOUR	New	6,720.00	3,360.00
8	SPRAY PAINTING	New	3,200.00	2,000.00
9	CHANGE LANE ASSIST SYSTEM CALIBRATION	New	840.00	840.00
Gross Labour Cost (\$)			12,920.00	7,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >