

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001779/UPS3Q2

Date: 27/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJX3965B	Insured Vehicle No :	SHD4831B
Date of Loss: 27/01/2020	Nature of Claim: TP	Claim No: MCT20010610

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX3965B	Engine No:	L13Z11705714
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	MRHGE68509P022413
Reg. Date:	10/06/2010 (Man. Year: 2009)	Odometer:	149479 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,242.96	3,343.12	4,899.84	59.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	1,940.00	1,580.00	44.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,762.96	5,283.12	6,479.84	55.09
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	11,762.96	4,000.00	7,762.96	65.99
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	03/02/2020	
Date Inspected:	06/02/2020 Inspected At:	BLK 10 KAKI BUKIT ROAD 2 #01-03 FIRST EAST CENTRE SINGAPORE 417868 Repairer: Profi Automotive (KB)
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2020)
Parts:	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX3965B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	540.80 FL	*466.30 FL
2	1		*REAR BUMPER SIDE RETAINER	O/S Bent	59.60 FL	*29.80 FL
3	1		*REAR RH FENDER	Repair	827.50 FL	*- FL
4	1		*FRONT RH DOOR PANEL	Bent	881.90 FL	*751.30 FL
5	1		*FRONT RH DOOR FRAME STICKER	Necessary	55.00 FL	*55.00 FL
6	1		*FRONT RH DOOR GLASS REGULATOR MOTOR	Not Necessary	505.20 FL	*- FL
7	1		*FRONT RH DOOR LOCK ASSY	Not Necessary	355.00 FL	*- FL
8	1		*FRONT RH DOOR LOCK STRIKER	Not Necessary	42.00 FL	*- FL
9	1		*FRONT RH DOOR WEATHERSTRIP	Necessary	104.30 FL	*104.30 FL
10	1		*FRONT RH DOOR INNER TRIM	Not Necessary	551.00 FL	*- FL
11	1		*REAR RH DOOR PANEL	Dented / Bent	846.10 FL	*702.50 FL
12	1		*REAR RH DOOR FRAME STICKER	Necessary	55.00 FL	*55.00 FL
13	1		*REAR RH DOOR CHECKER	Not Necessary	65.00 FL	*- FL
14	1		*REAR RH DOOR HINGE UPPER	Not Necessary	55.00 FL	*- FL
15	1		*REAR RH DOOR HINGE LOWER	Not Necessary	55.00 FL	*- FL
16	1		*REAR RH DOOR WEATHERSTRIP	Necessary	102.20 FL	*102.20 FL
17	1		*REAR RH DOOR INNER TRIM	Not Necessary	551.00 FL	*- FL
18	1		*REAR AXLE BEAM	Not Necessary	1,389.30 FL	*- FL
19	1		*REAR LH WHEEL HUB AND BEARING	Not Necessary	150.30 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
21	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
22	1		*SET REAR DOOR INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
23	1		*RIM	Dented / Bent	400.00 FS	*300.00 FS
24	1		*BOT BRAKE FULD	Not Necessary	60.00 FS	*- FS
25	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
26	1		*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
27	1		*REAR BUMPER LOWER GARNISH	Torn	800.00 FS	*600.00 FS
28	1		*SILL GARNISH O/S	DeepCut	900.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,681.20	3,796.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,438.24	453.28
Total Parts (\$\$)	8,242.96	3,343.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	20.00
2	REMOVE REFIT REAR LINING ,TRIM AND GARNISH	New	150.00	60.00
3	REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	40.00
4	REMOVE AND REFIT REAR RH QUARTER GLASS	New	120.00	0.00
5	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	New	120.00	60.00
6	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	New	150.00	0.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	600.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	1,100.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	60.00
Gross Labour Cost (\$)			3,520.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >