



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2004112
INV Date 22/05/2020
Reference CC6/CTI20001787/Aka3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 1605Y
Insured Veh. YL 8517P
Claim No. SNM20D200650C02/7
Policy No. DMCVSN1810641901
Accident Date 30/01/2020
Inspection Date 31/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI20001787/Aka3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 22-05-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 8517P	Veh. Inspected	GBJ 1605Y	
Policy No.	DMCVSN1810641901	Coverage (\$)	0.00	
Claim No.	SNM20D200650C02/7	Excess (\$)	0.00	
Assign From		Assign Date	31/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	FEA01BA30030	Colour	WHITE	
Odometer	28416	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	165 R13	BRIDGESTONE	6 mm	
L/H Rear Tyre	165 R13	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/01/2020	Inspection Date	31/01/2020	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 1605Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL	NOT NECESSARY	2,297.00	-
1	FRONT CORNER PANEL	CRACKED	566.00	482.00
1	FRONT CORNER PANEL CAP	NOT NECESSARY	62.00	-
1	FRONT SIDE VIEW MIRROR (BIG)	NOT NECESSARY	201.00	-
1	FRONT SIDE VIEW MIRROR (SMALL)	CUT	159.00	159.00
1	FRONT SIDE VIEW MIRROR STAND	NOT NECESSARY	459.00	-
1	FRONT GRILLE ASSY	CRACKED	565.00	565.00
8	FRONT GRILLE CLIP @\$8.00	NECESSARY	64.00	15.00
1	FRONT BUMPER	DISTORTED	838.00	732.00
1	FRONT L/H BUMPER SIDE COVER	MISSING	360.00	360.00
1	FRONT L/H HEADLAMP ASSY	MISSING	561.00	461.00
1	FRONT L/H HEADLAMP LOWER RUBBER	MISSING	36.00	36.00
1	FRONT L/H HEADLAMP PANEL	TO REPAIR SEE LABOUR	1,620.00	-
1	FRONT L/H SIDE LAMP	CRACKED	282.00	195.00
1	FRONT L/H SIGNAL LAMP	CRACKED	317.00	266.00
1	FRONT L/H DOOR	DISTORTED	2,381.00	2,001.00
2	FRONT L/H DOOR HINGE @\$222.00	BENT	444.00	258.00
1	FRONT L/H DOOR LOWER AIR DUCT	CRACKED	82.00	82.00
1	FRONT L/H DOOR LOCK	NOT NECESSARY	691.00	-
1	FRONT L/H DOOR WEATHERSTRIP	NOT NECESSARY	440.00	-
1	FRONT L/H DOOR INNER TRIM BOARD	NOT NECESSARY	650.00	-
1	FRONT L/H DOOR WINDOW MOTOR & REGULATOR ASSY	NOT NECESSARY	1,443.00	-
1	FRONT L/H DOOR PILLAR	TO REPAIR SEE LABOUR	1,833.00	-
1	FRONT L/H STEP GARNISH	CRACKED	563.00	346.00
1	FRONT L/H ARCH PANEL	NOT NECESSARY	423.00	-
1	FRONT L/H ARCH PANEL TOP GARNISH	NOT NECESSARY	246.00	-
	LESS 10% DISCOUNT		-	-595.80
			17,583.00	5,362.20

Report Ref No. CC6/CTI20001787/Aka3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT L/H DOOR COMPANY STICKER (SN)	NECESSARY	300.00	150.00
1	FRONT L/H DOOR ROV STICKER (SN)	NECESSARY	80.00	30.00
			380.00	180.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT FRONT L/H DOOR ,LOCK ,GLASS ,WEATHERSTRIP,TRIM BOARD ,WINDOW MOTOR & REGULATOR ASSY .		280.00	80.00
	TO REMOVE & REFIT DASHBOARD .	NOT NECESSARY	450.00	-
	TO REMOVE & REFIT FRONT WINDSCREEN .	NOT NECESSARY	200.00	-
	GUM .	NOT NECESSARY	80.00	-
	TO CHECK WIRING .		100.00	30.00
	TUFF KOTE.		150.00	50.00
	TOWING FEE.	NOT NECESSARY	200.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT L/H HEADLAMP PANEL AND FRONT L/H DOOR PILLAR .		2,000.00	800.00
	SPRAY PAINTING.		1,800.00	700.00
			5,260.00	1,660.00
	GRAND TOTAL		23,223.00	7,202.20
RECOMMENDED COST OF REPAIRS				7,202.20

Report Ref No. CC6/CTI20001787/Aka3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.