



新福德車廠私人有限公司

CHINA TRADING

LLK

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

TUNGSAN FOOD INDUSTRIES PTE LTD

03/02/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China

Khancha

FEA01BA30030

1 202 20

Accident date: 30/01/2020

Estimated repair cost for vehicle no: GBJ1605Y MITSUBISHI CANTER FEA01BR2SDEK

CHASSIS: FEA01BA30030

3.0 '19

S/n	Qty	Items	U/price	Amount
1	1	Front Panel <i>Not Nec</i>		\$2,297.00 X
2	1	Front Corner Panel <i>cracked</i>		\$566.00 482
3	1	Front Corner Panel Cap <i>Not Nec</i>		\$62.00 X
4	1	Front Side View Mirror (Big) <i>new</i>		\$201.00 X
5	1	Front Side View Mirror (Small) <i>lit</i>		\$159.00 ✓
6	1	Front Side View Mirror Stand <i>new</i>		\$459.00 +
7	1	Front Grille Assy <i>cracked</i>		\$565.00 ✓
8	8	Front Grille Clip <i>new</i>	\$8.00	\$64.00 15
9	1	Front Bumper <i>Distorted</i>		\$838.00 732
10	1	Front L/H Bumper Side Cover <i>Missing</i>		\$360.00 ✓
11	1	Front L/H Headlamp Assy <i>Missing</i>		\$561.00 461
12	1	Front L/H Headlamp Lower Rubber <i>Missing</i>		\$36.00 ✓
13	1	Front L/H Headlamp Panel <i>Repair</i>		\$1,620.00 X
14	1	Front L/H Side Lamp <i>2 cracked</i>		\$282.00 195
15	1	Front L/H Signal Lamp		\$317.00 266
16	1	Front L/H Door <i>Distorted</i>		\$2,381.00 2001
17	1	Front L/H Door Company Sticker <i>Nec</i>		\$300.00 150(SN)
18	1	Front L/H Door ROV Sticker <i>Nec</i>		\$80.00 30(SN)
19	2	Front L/H Door Hinge <i>Bent</i>	\$222.00	\$444.00 258
20	1	Front L/H Door Lower Air Duct <i>cracked</i>		\$82.00 ✓
21	1	Front L/H Door Lock <i>Not Nec</i>		\$691.00 X
22	1	Front L/H Door Weatherstrip <i>Not Nec</i>		\$440.00 X
23	1	Front L/H Door Inner Trim Board <i>new</i>		\$650.00 X
24	1	Front L/H Door Window Motor & Regulator Assy <i>new</i>		\$1,443.00 X

25	1	Front L/H Door Pillar <i>Repair</i>	\$1,833.00 X
26	1	Front L/H Step Garnish <i>Cracked</i>	\$563.00 346
27	1	Front L/H Arch Panel <i>He M</i>	\$423.00 X
28	1	Front L/H Arch Panel Top Garnish <i>He M</i>	\$246.00 X

5958 S.N. 180

536220

Subtotal :- \$17,963.00

Labour charges

To remove & refit front L/H door, lock, glass, weatherstrip, trim board, window motor & regulator assy

~~\$280.00~~ 80

To remove & refit dashboard

\$450.00 X

To remove & refit front windscreen

\$200.00 X

Gum

\$80.00 X

To check wiring

~~\$100.00~~ 30 1660

Tuff kote

~~\$150.00~~ 50

Towing fee

\$200.00 X

Panel beating

~~\$2,000.00~~ 800

Spray painting

~~\$1,800.00~~ 700

Subtotal :- \$5,260.00

Total :- \$23,223.00

Total: 7202-20
(P/P)

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: