Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001789/KES3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700021942

Claimant
Vehicle No: SMR1623Y

Insured Vehicle No: SLQ1073B

Date of Loss: 31/01/2020 Nature of Claim: TP Claim No: 5953435474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMR1623Y

Make & Model: HONDA VEZEL, 1.5 X SENSING (A) Engine No: LEB6740653
Reg. Date: 20/12/2019 (Man. Year: 2018) Chassis No: RU31320642
Colour: Metallic Red Odometer: 10319 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
Front Right Side: Dunlop 9 mm
Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,090.24	1,776.24	314.00	15.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,095.00	615.00	35.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,800.24	2,871.24	929.00	24.45
+ GST 7.00/7.00% (S\$)	266.02	200.99	65.03	24.45
Nett Amount (S\$)	4,066.26	3,072.23	994.03	24.45
t Loop of Upp // O v S	207 00/4 (CC)	204.60		

+ Loss of Use (4.0 x S\$97.90/day) (S\$) 391.60 + Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 3,465.83

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 04/02/2020 Inspected At: Optima Werkz Pte Ltd (HQ)

6 Kung Chong Road Singapore 159143

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAILGATE	Bent	972.40 FL	*972.40 FL	
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	45.80 FL	*45.80 FL	
3	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.30 FL	*75.30 FL	
4	1		*REAR WINDSCREEN SEALANT	Necessary	64.00 FS	*40.00 FS	
5	1		*REAR WINDSCREEN RUBBER	Serviceable	74.40 FL	*- FL	
6	10		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	58.00 FL	*- FL	
7	1		*REAR BUMPER	Buckled	787.90 FL	*745.30 FL	
8	8		*REAR BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL	
9	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL	
10	2		*REAR WINDSCREEN STOPPER	Necessary	30.00 FS	*30.00 FS	
11	1		*REAR BUMPER REVERSE SENSOR	Dented	350.00 FS	*200.00 FS	
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$)				2,501.80	2,152.80	
- List Item Discount on L Items 20.00/20.00% (S\$)					411.56	376.56	
				Total Parts (S\$)	2,090.24	1,776.24	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES TO REMOVE,REPLACE ,REPAIR ,READJUST REAR ACCIDENT AREAS & ETC	New	600.00	400.00
2	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	80.00	50.00
3	LABOUR CHARGES TO REMOVE & REPLACE ,REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT ,REAR WINDSCREEN RUBBER & ETC .TO EFFECT REPLACE AT REAR TAILGATE	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC TO EFFECT REPLACE OF REAR TAILGATE	New	120.00	60.00
5	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR END PANEL & REAR BUMPER & ETC	New	700.00	450.00
6	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM	New	60.00	15.00
	Gross Labou	1,710.00	1,095.00	
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >