



Section A - Accident Details	
Registration Number	SHD6350J
Case Reference Number	TAX/09/19/2045
Registration Date	20/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA CHEE KHIAN
Type of Accident	Side Swipe
Accident Date and Time	13/9/2019 1:10 PM
Accident Reported Date and Time	14/9/2019 10:02 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	13/9/2019 1:36 PM
Replacement Vehicle issued?	No
Job Card Number	24103351
Special Instruction to ARC, if any	TOWED \$60 / BP
Prepared Date and Time	14/9/2019 12:14 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$250.00
Total Spray Cost	\$936.00	\$300.00
Total Spare Part Cost	\$4,260.87	\$1,741.75
Total Other Cost	\$424.00	\$120.00
TOTAL COST	\$8,127.87	\$2,411.75
Lump Sum Total	\$6,150.00	\$2,400.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	16/09/2019 5:52 PM	16/09/2019 3:50 PM
Signature		
Remarks		Lumsum repair, Take after spray



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4 Singapore 757705
 FAX Number 63685592
 Estimator Telephone Number 68662623
 Accident Reporting Number 68662672

Date Generated : 27/09/2019
 User ID : PohSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1909-0437	Invoice Number	
Quotation Date	25.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$507.00	\$250.00
Total Labour	\$507.00	\$250.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$936.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TOWING CHARGE	\$84.00	\$60.00
Total Other Costs	\$424.00	\$120.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given ✓
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace ✓
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57014-47030	ARM SUB-ASSY.FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
		57013-47030	ARM SUB-ASSY.FR BUMPER RH	1.00	\$250.40	25.00	\$187.80	Replace	Replace ✓
		52127-47930	COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$13.88	Replace	Replace ✓
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given X
		81511-47050	LENS & BODY.FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace ✓
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number: 63688592
 Estimator Telephone Number: 68662623
 Accident Reporting Number: 68662672

Date Generated : 27/09/2018
 User ID : PehSuen

	81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓
	53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
	53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X
	53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	X
Total				\$6,736.51		\$2,177.19			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2177.19
 - 208

 1741.75
 + 250.00
 + 420.00

 2411.75
 4/5 \$2400/-

Estimator Assessment(s)

Surveyor Assessment(s)

Signature



Save Clear

Survey Date

16/09/2019

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed ~~and~~ is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Case Details

Case Reference Number : TAX/09/19/2045
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6350J

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8500-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 13/09/2019 05:10 AM
 Vehicle Age(In Months) : 46

Documents / Photographs

View Documents / Photographs Total Documents 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace * / DD
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace * / Nec
One Time Key In	Main			BUMPER SUPPORT FRH	1	78.40	78.40	25.00	57.30	Replace	1	57.30	Replace * / Nec
One Time Key In	Main			BUMPER SUPPORT FLH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check * X NN
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give * X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	1	187.80	Replace * / Nec
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace * / SCH

Total Spare Part Cost	5,326.09	Surveyor Total	2,177.19
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	4,260.87	Final Sur Total	1,741.75

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER GRILLE SUB-ASSY.LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	* / SCH
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			LENS & BODY.FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace	* / SCH
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	* X NN
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	* / SCH
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give	* X NN SVC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	* X NN SVC
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check	* X NN
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Check	* X NN
Total Spare Part Cost									5,326.09	Surveyor Total		2,177.19		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,260.87	Final Sur Total		1,741.75		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	507.00	250	
Total:			507.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
Total:			378.00	200.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
3	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100	
Total:			936.00	300.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ NPC
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	60.00	20	✓ NPC
3	Main	TO WASH AND VACUUM	60.00	0	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	✓ NPC
5	Main	TOWING CHARGE	84.00	60	✓
Total:			424.00	60.00 120	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,260.87	1,741.75
Total Labour Cost	507.00	250.00
Total Spray Painting	936.00	300.00
Other	424.00	60.00
Overall Total	6,127.87	2,787.19
Lump Sum Repair Option		✓
Lump Sum Total	6,150.00	2,800.00
Surveyor Approved Amount		2,800.00
No of Repair Days*	5	3
Remarks		Lumpsum repair, Take after spray
Surveyor Name		STEVE CHEN