



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004851
INV Date 09/07/2020
Reference CC4/FCI20001798/Kea3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SGF 8684J
Insured Veh. SHD 6788E
Claim No. D20000712MFSH
Policy No. D-20094922MFSH
Accident Date 30/01/2020
Inspection Date 31/01/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20001798/Kea3q2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 09-07-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6788E	Veh. Inspected	SGF 8684J
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20000712MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	31/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107118317	Colour	METALLIC GOLD
Odometer	250994	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	MICHELIN	7 mm
L/H Front Tyre	185/70 R14	MICHELIN	7 mm
R/H Rear Tyre	185/70 R14	MICHELIN	6 mm
L/H Rear Tyre	185/70 R14	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/01/2020	Inspection Date	31/01/2020
Survey held at	SLP MOTORING SERVICES 102 GERALD DRIVE #04-75 SELETAR SPRINGS CONDOMINIUM SINGAPORE 798593		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 8684J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	BENT	685.00	685.00
1	REAR BOOT LID '1.6'	NECESSARY	35.49	35.49
1	REAR BOOT LID 'COROLLA'	NECESSARY	54.47	54.47
1	REAR BOOT LID 'ALTIS'	NECESSARY	45.20	45.20
1	REAR BOOT LID TOP LOCK	DENTED	61.00	61.00
2	REAR BOOT LID LEFT & RIGHT SIDE REFLECTOR @\$233.80	O/S BROKEN	467.60	233.80
1	REAR BOOT LID TOP COVER BOARD	NO SUCH PARTS	162.00	-
1	REAR BOOT LID OUTER CHROME HANDLE	SERVICEABLE	246.00	-
1	REAR END PANEL	BENT	486.80	486.80
1	REAR END PANEL LOCK GARNISH	CRACKED	177.73	177.73
8	REAR END PANEL LOCK GARNISH CLIPS @\$5.00	NECESSARY	40.00	40.00
1	REAR END PANEL JOINT SEALANT	NECESSARY	80.00	80.00
2	TAIL LAMP (LEFT & RIGHT) @\$315.00	O/S BROKEN	630.00	315.00
2	TAIL LAMP APRON (LEFT & RIGHT) @\$55.00	BENT	110.00	110.00
1	REAR BUMPER	TORN	435.00	435.00
10	REAR BUMPER CLIPS @\$50.00	NECESSARY	50.00	50.00
1	REAR BUMPER CENTRE REINFORCEMENT	NO SUCH PARTS	232.00	-
1	REAR BUMPER SPONGE	NO SUCH PARTS	125.00	-
2	REAR BUMPER BRACKET	BENT / DISTORTED	158.00	158.00
2	REAR BUMPER SIDE RETAINER (LEFT & RIGHT) @\$59.50	CRACKED	119.00	119.00
2	REAR BUMPER LEFT & RIGHT SIDE LOWER RETAINER @\$47.64	CRACKED	95.00	95.00
1	REAR EXHAUST SILENCER	BENT	728.00	728.00
1	REAR SPARE TYRE TANK FLOOR PANEL	BENT / BUCKLED	757.00	757.00
2	REAR SPARE TYRE TANK LEFT & RIGHT SIDE PANEL @\$249.00	O/S BENT	498.00	249.00
1	REAR NUMBER PLATE WITH CASING	SERVICEABLE	100.00	-
2	REAR LEFT & RIGHT SIDE MUDGUARD @\$860.10	O/S BUCKLED	1,720.20	860.10
2	REAR LEFT & RIGHT SIDE MUDGUARD INNER TRIM COVER @\$295.80	O/S DEFORMED	591.60	295.80
2	REAR LEFT & RIGHT SIDE MUDGUARD LOWER AIR DUCT @\$115.00	SERVICEABLE	230.00	-

Report Ref No. CC4/FCI20001798/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	REAR LEFT & RIGHT SIDE MUDGUARD INNER COWLING @\$119.80	SERVICEABLE	239.60	-
8	REAR RIGHT SIDE MUDGUARD INNER COWLING CLIPS @\$3.90	NOT NECESSARY	31.20	-
8	REAR LEFT SIDE MUDGUARD INNER COWLING CLIPS @\$3.90	NOT NECESSARY	31.20	-
1	REAR WINDSCREEN MOULDING	NECESSARY	85.00	85.00
	LESS 25% DISCOUNT		-	-1,539.10
			9,507.09	4,617.29
1	REAR BOOT LID RUBBER (50%) (SN)	DISTORTED / DENTED	165.00	82.50
			165.00	82.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSE SENSOR (SN)	TORN	350.00	200.00
			350.00	200.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE REAR WINDSCREEN.		180.00	120.00
	TO APPLY SILICON ONTO REAR WINDSCREEN.		90.00	40.00
	TO APPLY ANTI-RUST ON THE ACCIDENT AFFECTED AREA.		120.00	120.00
	TO CHECK ELECTRICAL WIRING FOR PROPER FUNCTIONALITY AND TEST REAR REVERSE SENSOR .		120.00	70.00
	TO CONDUCT WATER LEAKAGE TEST.		50.00	30.00
	TO REMOVE AND REPLACE REAR EXHAUST ASSY .		120.00	60.00
	STRAIGHTENING ,REPAIRING AND REALIGNING ON THE AFFECTED AREA ,CUTTING REAR TWO SIDE MUDGUARD ,REAR END PANEL,DISMANTLE AND REPLACE THE ABOVE MENTIONED PARTS.		2,000.00	1,800.00
	SPRAY PAINTING FOR ALL ACCIDENT AFFECTED PARTS ,REAR BUMPER,REAR END PANEL,REAR BOOT LID ,REAR LEFT AND RIGHT SIDE MUDGUARD PANELS.		1,500.00	1,300.00
			4,180.00	3,540.00
GRAND TOTAL			14,202.09	8,439.79

Report Ref No. CC4/FCI20001798/Kea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00
---	--	--	----------

Report Ref No. CC4/FCI20001798/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGF 8684J

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

