Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001799/KES3Q2

Date: 20/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700030555

Claimant
White No: SBW8288P

Vehicle No: SWK5203L Insured vehicle No: SBW8288P

Date of Loss: 12/01/2020 Nature of Claim: TP Claim No: 5303717956SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK5203L

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: LEB7104444

Reg. Date: 12/04/2019 (Man. Year: 2018) Chassis No: GP72003397

Colour: Metallic Dark Blue Odometer: 40468 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Yokohama 2 mm Rear Left Side: Firenza 8 mm
Front Right Side: Yokohama 2 mm Rear Right Side: Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,294.24	1,440.80	853.44	37.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	845.00	505.00	37.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,644.24	2,285.80	1,358.44	37.28
+ GST 7.00/7.00% (S\$)	255.10	160.01	95.09	37.28
Nett Amount (S\$)	3,899.34	2,445.81	1,453.53	37.28
+ Car Rental (4.0)	(S\$78.00/day) (S\$)	312.00		

(4.0 x 3\$70.00/day)	312.00
(\$\$)	2,757.81
Liable Amount (50.00%) (S\$)	1,378.91
+ Doc/Search Fee (S\$)	7.45
Nett Liability (S\$)	1,386.36
Global Sum Settlement (S\$)	1,380.00

INSPECTION

Date of Assignment: 31/01/2020

Date Inspected: 02/03/2020 Inspected At: Esteem Performance Pte Ltd (HQ)

Blk 5033 Ang Mo Kio Ind Park 2, #01-

259

Singapore 569536

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	1,150.00 FL	*1,150.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	28.00 FL	*28.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	15.40 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	15.40 FL	*- FL
5	1		*RH FRONT FENDER	Bent	535.00 FL	*535.00 FL
6	1		*RH FRONT FENDER UNDERSHIELD	Serviceable	110.50 FL	*- FL
7	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	28.00 FL	*- FL
8	1		*RHF FENDER WORDING HYBRID	Necessary	88.00 FL	*88.00 FL
9	1		*RH FRONT RIM	Serviceable	390.00 FL	*- FL
10	1		*RH FRONT TYRE	Serviceable	250.00 FS	*-FS
11	1		*RH FRONT HUP CAP	Serviceable	195.00 FL	*- FL
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	2,805.30	1,801.00
- List Item Discount on L Items 20.00/20.00% (S\$)					511.06	360.20
				Total Parts (S\$)	2,294.24	1,440.80
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER)	New	600.00	400.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER)	New	600.00	400.00
3	TO TUFF COAT	New	100.00	30.00
4	TO CHECK WIRING	New	50.00	15.00
	Gross Labou	r Cost (S\$)	1,350.00	845.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.