

SMK 5203 L Finalised

1,097.00

219.40

\$ (801-00

Repair Estimates

Parts (a) Cost / List Price Items

Plus/Less 20%

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Not Normania

Total of Cost / List	<u>\$ (440-%) 877.60</u>
(b) Nett Price Items	
Less	
Total of Nett Item	
(c) Special Nett Items	
Total Parts Cost	\$ 877.60
Labour	\$ \(\gamma \lambda \tau \tau \rangle \tau \
Total	\$ 7777 % 2,227.60
The above total will be subjected to 75	% G.S.T.
	_
Name of Surveyor	Kennerb UKK 2/3/20 at
Company	· CKK
Survey conducted on	:2/3/20_at
Remarks By Surveyor	
·	uthorized / is not authorized until further notice.
(b) Recommended Days of Repa	
(c) Resurvey	: Required / Not Required
	. Negalied / Not Negalied
(d) Excess	:\$
(e) Signature of surveyor	:



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

_			_	
S	na	rΔ	Pa	rts

Vehicle No. :	SMK 5203 L	Submit By	:	SERENCE
Make & Model:	HONDA SHUTTLE	Year Manufacture		2018
Chassis No :	GP72003397	Engine No.	:	**************************************
•		Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper	Bulom	1	4120.00		Garveyor
2	Front bumper clip	M	10	28.00		
3	Front bumper side retainer LH	Sh	1	15-40		×
4	Front bumper side retainer RH	5~	1	:12.10		Y
5	RH front fender	R	. 1	53500		
6	RH front fender undershield	Su,	1	110:00		X
7	RH front fender undershield clip	n	10	.28.00		X
8	RHF fender wording "HYBRID"	N	1	37.00		
9	RH front rim	Sm	11	390.00		X
10	RH front tyre	14	. 1	XV (U)	SM	~
11	RH front hup cap	<u> </u>	~ 1	195.00		X
12						
13						
14						
15						
16						
17						
18						
19						
20	,			, , , , , , , , , , , , , , , , , , ,		
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Lat	ooui	r
Las	JUUI	

Vehicle No.	:	SMK 5203 L	Submit By	:		SERENCE	
Make & Model	: _	TOYOTA PRIUS	Year of Manufacture	:		2017	
S/No		Labour Description			imated	Adjusted	HCOM.
			į.		Dut	Duina	

S/No	Labour Description	Esimated	Adjusted
		Price	Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER, RHF FENDER)	\$600.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER, RHF FENDER)	\$600.00	4001
3	To tuff coat.	\$100.00	301
<u> </u>	TO Observativities	φ C Λ ΛΛ	40öl 301 152
3	TO Check wiring	\$50.00	,,,
_			
<u> </u>	•		
-			
 			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.