

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001805/UEA3Q2
Date: 06/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100381673
Claimant Vehicle No :	FBN1036T	Insured Vehicle No :	GBD2428S
Date of Loss:	10/01/2020	Nature of Claim:	TP
		Claim No:	7712245631SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1036T		
Make & Model:	YAMAHA TMAX530, 530cc CVT ABS	Engine No:	J409E049790
Reg. Date:	06/02/2015 (Man. Year: 2014)	Chassis No:	JYASJ099000002281
Colour:	Red	Odometer:	0 km
Engine Capacity:	530 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	160/50 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,143.30	4,562.00	2,581.30	36.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	785.00	595.00	43.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,523.30	5,347.00	3,176.30	37.27
Approved Total (Overridden) (S\$)		4,200.00		

Nett Amount (S\$)	8,523.30	4,200.00	4,323.30	50.72
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 03/02/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Bent / Twisted	980.00 FL	*980.00 FL
2	1		*FORK UNDER BRACKET COVER	Bent	190.00 FL	*190.00 FL
3	1		*FRONT SPORT RIM	Bent	550.00 FL	*550.00 FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Serviceable	52.00 FL	*- FL
6	1		*WINDSHIELD	Scratched	248.00 FL	*248.00 FL
7	1		*HEADLAMP	Cracked	550.00 FL	*550.00 FL
8	1		*SIDE MIRROR	Cut	120.00 FL	*120.00 FL
9	1		*HANDLE-BAR	Bent	135.00 FL	*135.00 FL
10	1		*HANDLE-BAR BALANCERS	O/S Scratched	160.00 FL	*80.00 FL
11	1		*SET HAND GRIP	Necessary	90.00 FL	*90.00 FL
12	1		*BRAKE LEVER	Scratched	52.00 FL	*52.00 FL
13	2		*FRONT SIGNALS	Cracked	250.00 FL	*250.00 FL
14	1		*LAMPSTAY	Bent	225.00 FL	*145.00 FL
15	1		*MAIN STAND	Repair	145.00 FL	*- FL
16	1		*SET FAIRING COVER (ASSY)	Cut / Cracked	1,150.00 FL	*1,150.00 FL
17	1		*SET NUMBER PLATE	FRT Necessary	28.00 FS	*10.00 FS
18	1		*REAR BOX	Serviceable	280.00 FS	*- FS
19	1		*REAR BOX BRACKET	Not Necessary	150.00 FS	*- FS
20	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
21	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
22	1		*SET STEERING CONE	Necessary	120.00 FS	*120.00 FS
23	1		*ENGINE COVER PROTECTOR	Cut	90.00 FS	*90.00 FS
24	1		*EXHAUST PIPE GUARD	Cut	75.00 FS	*75.00 FS
25	1		*SET FORK SLIDER	Cut	95.00 FS	*95.00 FS
26	1		*AKRAPONIC EXHAUST PIPE	Serviceable	1,650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,651.00	5,016.00
- List Item Discount on L Items 10.00/10.00% (\$)	507.70	454.00
Total Parts (\$)	7,143.30	4,562.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	450.00	300.00
4	TO RESPRAY PAINTING	New	800.00	450.00
Gross Labour Cost (S\$)			1,380.00	785.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >