

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001806/UDA3Q2
Date: 20/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100495693
Claimant
Vehicle No : SJS9427A **Insured Vehicle No :** SKH1132Z
 Date of Loss: 31/01/2020 Nature of Claim: TP Claim No: 9455837934SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS9427A**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4930449
 Reg. Date: 16/09/2009 (Man. Year: 2009) Chassis No: MR053ZEE106154544
 Colour: Beige Odometer: 74228 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,442.22	8,391.40	8,050.82	48.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	4,120.00	1,730.00	29.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,292.22	12,511.40	9,780.82	43.88
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	22,292.22	10,000.00	12,292.22	55.14
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		11,436.45		

INSPECTION

Date of Assignment: 03/02/2020
 Date Inspected: 03/02/2020 Inspected At: Zoom Autowerks Pte Ltd (HQ)
 130 Bedok Reservoir Road, Eunos
 Spring, #08-1339
 Singapore 470130
 Estimated Period of Repair: 13.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	683.83 FL	*683.83 FL
2	1		*FRONT BUMPER TOP RUBBER	Necessary	145.00 FL	*145.00 FL
3	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	96.00 FL	*- FL
4	2		*FRONT BUMPER RETAINER	Not Necessary	92.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	340.00 FL	*340.00 FL
6	1		*FRONT BUMPER CENTRE AIR -GRILLE	Torn	185.34 FL	*185.34 FL
7	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	210.00 FL	*- FL
8	2		*FRONT BUMPER FOG LAMP	Not Necessary	435.20 FL	*- FL
9	2		*FRONT BUMPER FOG LAMP RING	Not Necessary	150.00 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FL	*50.00 FL
11	1		*FRONT GRILLE	Bent / Cracked	631.00 FL	*631.00 FL
12	1		*FRONT GRILLE LOGO	Necessary	61.00 FL	*61.00 FL
13	10		*FRONT GRILLE CLIPS	Not Necessary	40.00 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Bent	608.00 FL	*608.00 FL
15	1		*FRONT CENTRE BRACE PANEL	Twisted	97.00 FL	*97.00 FL
16	1		*HORN	Not Necessary	71.00 FL	*- FL
17	2		*FRONT HEADLAMP ASSY	Cracked	1,250.30 FL	*1,250.30 FL
18	2		*FRONT HEADLAMP BRACKET	No such part	80.20 FL	*- FL
19	2		*FRONT FENDER	Repair	660.20 FL	*- FL
20	2		*FRONT FENDER EMBLEM	Not Necessary	76.00 FL	*- FL
21	2		*FRONT FENDER INNER SHIELD	Not Necessary	284.00 FL	*- FL
22	20		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FL	*- FL
23	1		*BONNET	Repair	690.00 FL	*- FL
24	1		*BONNET LOCK	Twisted	91.00 FL	*91.00 FL
25	1		*BONNET INSULATOR	Not Necessary	224.00 FL	*- FL
26	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	40.00 FL	*- FL
27	2		*BONNET HINGE	Not Necessary	110.00 FL	*- FL
28	1		*AC CONDENSER ASSY	Bent / Punctured	1,431.84 FL	*1,431.84 FL
29	1		*RADIATOR ASSY	Not Necessary	1,651.70 FL	*- FL
30	1		*RADIATOR EXPANSION TANK	Not Necessary	135.00 FL	*- FL
31	1		*RADIATOR COWLING	Not Necessary	206.00 FL	*- FL
32	1		*RADIATOR FAN MOTOR	Not Necessary	310.62 FL	*- FL
33	1		*RADIATOR TOP BRACKET	Not Necessary	82.40 FL	*- FL
34	1		*AC FAN COWLING	Not Necessary	256.00 FL	*- FL
35	1		*AC FAN MOTOR	Not Necessary	295.00 FL	*- FL
36	1		*AC CONDENSER PIPE (BIG)	Not Necessary	225.00 FL	*- FL
37	1		*AC COMPRESSOR PIPE (SMALL)	Not Necessary	195.00 FL	*- FL
38	1		*REAR BUMPER	Distorted	660.12 FL	*660.12 FL
39	2		*REAR BUMPER RETAINER	Not Necessary	120.00 FL	*- FL
40	2		*REAR BUMPER BRACKET	Dented	80.10 FL	*80.10 FL
41	1		*REAR BUMPER SPONGE	Torn	181.54 FL	*181.54 FL
42	1		*REAR BUMPER REINFORCEMENT	No such part	256.00 FL	*- FL
43	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
44	2		*REAR BUMPER REFLECTOR	Not Necessary	62.00 FL	*- FL
45	1		*BOOTLID	Bent / Buckled	691.50 FL	*691.50 FL
46	1		*BOOTLID BADGE	Necessary	52.00 FL	*52.00 FL
47	1		*BOOTLID BADGE 1.6E	Necessary	48.00 FL	*48.00 FL
48	1		*BOOTLID BADGE VVTI	Necessary	48.00 FL	*48.00 FL
49	1		*BOOTLID BADGE ALTIS	Necessary	52.00 FL	*52.00 FL
50	1		*BOOTLID BADGE COROLLA	Necessary	48.00 FL	*48.00 FL
51	1		*BOOTLID OUTER GARNISH	Not Necessary	182.90 FL	*- FL
52	10		*BOOTLID OUTER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
53	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	84.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*BOOTLID LAMP	Not Necessary	385.00 FL	*- FL
55	2		*BOOTLID LAMP INNER SEAL	Not Necessary	60.00 FL	*- FL
56	4		*BOOTLID LAMP CLIPS	Not Necessary	40.00 FL	*- FL
57	1		*BOOTLID INNER LOCK	Twisted	86.30 FL	*86.30 FL
58	1		*BOOTLID CATCH	Not Necessary	75.20 FL	*- FL
59	1		*BOOTLID WEATHER STRIP	Twisted	165.20 FL	*165.20 FL
60	2		*REAR TAILLAMP	Cracked	902.00 FL	*902.00 FL
61	2		*REAR TAILLAMP SEALER	Necessary	60.00 FL	*60.00 FL
62	2		*REAR TAILLAMP PANEL	Repair	342.00 FL	*- FL
63	1		*REAR END PANEL	Dented	595.00 FL	*595.00 FL
64	1		*REAR END PANEL TOP GARNISH	Twisted	175.00 FL	*175.00 FL
65	2		*REAR FENDER	Repair	2,062.00 FL	*- FL
66	2		*REAR FENDER INNER TRIMS	Deformed / Torn	270.00 FL	*270.00 FL
67	20		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FL	*- FL
68	1		*SPARE TYRE PANEL	Buckled	796.50 FL	*796.50 FL
69	1		*SPARE TYRE TOP BOARD	Torn	256.30 FL	*256.30 FL
70	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
71	1		*FRONT NUMBER PLATE WITH GARNISH	Bent	55.00 FS	*40.00 FS
72	1		*REAR NUMBER PLATE WITH GARNISH	Not Necessary	55.00 FS	*- FS
73	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	45.00 FS	*- FS
74	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,766.29	11,086.87
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,324.07	2,695.47
Total Parts (\$\$)	16,442.22	8,391.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS	New	1,200.00	750.00
2	TO PUTTY, SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS	New	1,200.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	1,200.00
5	TO PUTTY, SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,200.00	1,100.00
6	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	150.00	0.00
7	TO CONDUCT AC LEAKAGE TEST & TOP UP AC GAS	New	150.00	100.00
8	TO RE-POSITION & INSTALL REVERSE SENSOR	New	150.00	50.00
9	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
10	TO RUST PROOF AFFECTED AREAS	New	100.00	100.00
Gross Labour Cost (S\$)			5,850.00	4,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >