

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001809/UDA3N2

Date: 21/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900151083

Claimant
Vehicle No : SKK2518Y **Insured Vehicle No :** SLS5050E

Date of Loss: 24/01/2020 Nature of Claim: TP Claim No: 9147790663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK2518Y		
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Engine No:	CAXD21924
Reg. Date:	24/06/2013 (Man. Year: 2013)	Chassis No:	WVWZZZ16ZDM073502
Colour:	Black	Odometer:	103217 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,095.37	3,911.20	9,184.17	70.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,750.00	2,150.00	55.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,995.37	5,661.20	11,334.17	66.69
Approved Total (Overridden) (\$\$)		4,500.00		
Nett Amount (\$\$)	16,995.37	4,500.00	12,495.37	73.52
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,807.45		

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 03/02/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
130 Bedok Reservoir Road, Eunos
Spring, #08-1339
Singapore 470130

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,196.50 FL	*1,196.50 FL
2	1		*REAR BUMPER LOWER	Cut	583.70 FL	*583.70 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	297.20 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	494.70 FL	*494.70 FL
5	1		*REAR BUMPER BEAM GARNISH	Cracked	98.40 FL	*98.40 FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	297.60 FL	*- FL
7	2		*REAR BUMPER UNDER GARNISH	Not Necessary	168.40 FL	*- FL
8	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
9	1		*REAR BOOTLID PANEL	Repair	1,495.30 FL	*- FL
10	1		*REAR BOOTLID LOCK	Not Necessary	185.40 FL	*- FL
11	2		*REAR BOOTLID HINGE	Not Necessary	493.20 FL	*- FL
12	1		*REAR BOOTLID WEATHER STRIP	Twisted	287.20 FL	*287.20 FL
13	1		*REAR BOOTLID INNER TRIM	Not Necessary	190.70 FL	*- FL
14	1		*REAR BOOTLID LOGO	Necessary	97.60 FL	*97.60 FL
15	1		*REAR BOOTLID EMBLEM (JETTA)	Necessary	65.50 FL	*65.50 FL
16	1		*REAR BOOTLID EMBLEM (TSI)	Necessary	58.40 FL	*58.40 FL
17	2		*REAR BOOTLID REFLECTOR LAMP	Not Necessary	978.40 FL	*- FL
18	2		*REAR TAILLAMPS	Not Necessary	1,529.60 FL	*- FL
19	1		*REAR TAILLAMPS CLIPS	Not Necessary	20.00 FL	*- FL
20	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	184.80 FL	*- FL
21	2		*REAR FENDER COWLING	Not Necessary	624.80 FL	*- FL
22	2		*REAR FENDER INNER SIDE TRIM GARNISH	Not Necessary	993.60 FL	*- FL
23	1		*REAR END PANEL	Dented / Bent	967.60 FL	*755.10 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	156.80 FL	*156.80 FL
25	1		*REAR END PANEL LOCK SENSOR	Not Necessary	257.10 FL	*- FL
26	1		*REAR SPARE TYRE PANEL	Not Necessary	940.00 FL	*- FL
27	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	420.00 FL	*- FL
28	1		*REVERSE SENSOR	Shorted	450.00 FS	*200.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
30	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,752.50	4,103.90
- List Item Discount on L Items 5.00/5.00% (\$\$)	657.13	192.70
Total Parts (\$\$)	13,095.37	3,911.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & RENEW AFFECTED ACCIDENT AREAS	New	1,600.00	800.00
2	TO PUTTY, SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTA, REAR INTERIOR TRIMS ,SEAT ,CARPETS TO FACILITATE REPAIRS	New	250.00	80.00
5	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TO FACILITATE REPAIRS	New	250.00	0.00
6	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
7	TO RUST PROOF AFFECTED AREAS	New	100.00	50.00
Gross Labour Cost (\$\$)			3,900.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >