



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006611
INV Date 24/09/2020
Reference CC4/FCI20001816/Kka3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMA 6196U
Insured Veh. SHB 4138E
Claim No. D20000707MFSH/
Policy No. D-20094922MFSH
Accident Date 29/01/2020
Inspection Date 03/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD	Ref : CC4/FCI20001816/Kka3q2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Date : 24-09-2020
	Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4138E	Veh. Inspected	SMA 6196U
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20000707MFSH/	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	31/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZVW508037188	Colour	METALLIC GREY
Odometer	53830	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS
--	---

5. General Information

Accident Date	29/01/2020	Inspection Date	03/02/2020
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days
--	---



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 6196U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	112.70	112.70
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE	DENTED	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	MTG CRACKED	149.70	149.70
1	REAR BUMPER UNDER COVER	SERVICEABLE	355.20	-
1	TAIL LAMP LH-UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP LH-LOWER	CRACKED	511.60	511.60
1	LH REAR FENDER UNDERSHIELD	NOT NECESSARY	92.30	-
10	LH REAR FENDER UNDERSHIELD CLIP	NOT NECESSARY	30.00	-
	LESS 25% DISCOUNT		-845.49	-473.53
			2,536.46	1,420.57
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
<u>LABOUR</u>				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER ,END PANEL).		600.00	200.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA ,(REAR BUMPER ,END PANEL).		600.00	280.00
	TO CHECK WIRING .		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR .		120.00	50.00
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			1,570.00	550.00
GRAND TOTAL			4,306.46	1,970.57
RECOMMENDED COST OF REPAIRS				1,970.57

Report Ref No. CC4/FCI20001816/Kka3q2



Report Ref No. CC4/FCI20001816/Kka3q2

A handwritten signature in black ink, consisting of the letters 'KSC' in a cursive, stylized font.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 6196U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 6196U

RE-INSPECTION

