

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20001821/UGA3Q2

**Date:** 30/06/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
<b>Claimant Vehicle No :</b>	SKJ660L	<b>Insured Vehicle No :</b>	GBH817U
Date of Loss:	25/01/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0000229

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ660L		Engine No:	B5691283N20B20A
Make & Model:	BMW X3, 2.0 SDRIVE 20I LED SR NAV (A)		Chassis No:	WBAWY920200J00232
Reg. Date:	27/02/2016 (Man. Year: 2015)		Odometer:	64060 km
Colour:	Black			
Engine Capacity:	1997 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,573.20	2,535.88	2,037.32	44.55
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,060.00	450.00	610.00	57.55
Paintwork Labour	700.00	400.00	300.00	42.86
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,344.20</b>	<b>3,396.88</b>	<b>2,947.32</b>	<b>46.46</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	444.09	237.78	206.31	46.46
<b>Nett Amount (\$\$)</b>	<b>6,788.29</b>	<b>3,634.66</b>	<b>3,153.63</b>	<b>46.46</b>
<b>+ Loss of Use (3.0 x S\$90.00/day) (\$\$)</b>		270.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>3,912.11</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>3,900.00</b>		

### INSPECTION

Date of Assignment:	03/02/2020	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	12/02/2020	Inspected At:	Progressive Car Care Pte Ltd (HQ)
			Blk 3022A Ubi Road 1, #01-45/46
			Singapore 408716
Estimated Period of Repair:	3.0 days		

---

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
<b>Parts:</b>	M1-SUV	BMW X3 2.0 SDRIVE 20I LED SR NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKJ660L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT FENDER OUTER ARCH GARNISH - LH	Torn	180.70 F	*180.70 F
2	1	NA	*FRONT FENDER - LH	Badly Dented	808.05 F	*808.05 F
3	1	NA	*FRONT FENDER CHROME - LH	Not Necessary	71.75 F	*- F
4	10	NA	*FRONT FENDER COWLING CLIPS - LH	Necessary	50.00 F	*50.00 F
5	1	NA	*FRONT FENDER COWLING (FRONT) - LH	Not Necessary	134.70 F	*- F
6	1	NA	*FRONT FENDER COWLING (REAR) - LH	Not Necessary	134.70 F	*- F
7	1	NA	*FRONT MUDFLAP - LH (NPA)	Not Necessary	0.00 F	*- F
8	1	NA	*FRONT FOG LAMP COVER - LH	Not Necessary	75.45 F	*- F
9	1	NA	*FRONT FOG LAMP	Not Necessary	453.25 F	*- F
10	1	NA	*FRONT BUMPER	Cut	1,580.60 F	*1,580.60 F
11	10	NA	*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 F
12	1	NA	*FRONT BUMPER PROTECTOR /LOWER SPOILER - LH	Serviceable	290.50 F	*- F
13	4	NA	*FRONT BUMPER SENSOR	Not Necessary	952.20 F	*- F
14	4	NA	*FRONT BUMPER SENSOR RUBBER	Not Necessary	32.00 F	*- F
15	1	NA	*FRONT BUMPER SENSOR WIRE (NPA)	Not Necessary	0.00 F	*- F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>4,813.90</b>	<b>2,669.35</b>
<b>- Add. Disc. on L,N Items 5.00/5.00% (S\$)</b>	240.70	133.47
<b>Total Parts (S\$)</b>	<b>4,573.20</b>	<b>2,535.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer) (NECESSARY)	11.00	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	700.00	400.00
<b>Labour Items</b>				
2	TO KNOCK OUT DENTS; REMOVE; REPLACE ACCIDENT PARTS	New	700.00	300.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO TUFF-KOTE	New	120.00	30.00
5	TO 4 WHEEL ALIGNMENT	New	120.00	60.00
6	TO REMOVE; REPLACE/REFIX REAR BUMPER SENSOR	New	100.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>1,760.00</b>	<b>850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >