

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 20 May 2020

**Preliminary Advice**

|                    |                                                                                                          |                         |              |
|--------------------|----------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJN5845D                                                                                               | Accident Date           | : 11/01/2020 |
| TP Vehicle No      | : SMF348L                                                                                                | Assignment Date         | : 03/02/2020 |
| Make               | : HYUNDAI ELANTRA                                                                                        | Est. Duration of Repair | : 3.00       |
| Date of Inspection | : 19/05/2020                                                                                             |                         |              |
| Inspection At      | : CHENG HOE MOTOR PTE LTD (YISHUN)<br>BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A<br>SINGAPORE 768761 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 2,687.04 |
| Revised Amount              | :S\$ | 2,078.16 |
| Check Items (Estimated)     | :S\$ | 458.88   |
| Total                       | :S\$ | 2,537.04 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.