Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001892/R1PS3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant SME7845C Insured Vehicle No: SHA7035D

Vehicle No: SME7845C Insured Vehicle No: SHA7035D

Date of Loss: 26/01/2020 Nature of Claim: TP Claim No: MCT20010637

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME7845C

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 2NR5279276

Reg. Date: 17/10/2018 (Man. Year: 2018) Chassis No: MR2B23F3201151365

Colour: Grey Odometer: 69397 km

Engine Capacity: 1496 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm
Front Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|----------------------|------------|------------|--------|
| Parts | 1,902.75 | 507.75 | 1,395.00 | 73.31 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,510.00 | 400.00 | 1,110.00 | 73.51 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 3,412.75 | 907.75 | 2,505.00 | 73.40 |
| + GST 7.00/7.00% (S\$) | 238.89 | 63.54 | 175.35 | 73.40 |
| Nett Amount (S\$) | 3,651.64 | 971.29 | 2,680.35 | 73.40 |
| + Car Rental (2.0 x | S\$100.00/day) (S\$) | 200.00 | | |
| + D | oc/Search Fee (S\$) | 7.45 | | |
| | Nett Liability (S\$) | 1,178.74 | | |

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 03/02/2020 Inspected At: Sng Ah Tee Motor & Panel Service

Pte Ltd (Pioneer)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jul 2020)

Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SME7845C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

0----

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--------|----------------|-----------------------------------|--------------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 505.00 FL | *505.00 FL |
| 2 | 10 | | *REAR BUMPER CLIPS | Necessary | 55.00 FL | *55.00 FL |
| 3 | 1 | | *REAR BUMPER SIDE RETAINER | N/S Cut | 234.00 FL | *117.00 FL |
| 4 | 1 | | *REAR BUMPER REVERSE SENSOR | Serviceable | 770.00 FL | *- FL |
| 5 | 1 | | *REAR BUMPER REINFORCEMENT | Serviceable | 345.00 FL | *- FL |
| 6 | 1 | | *REAR BUMPER REFLECTOR (LH) | Serviceable | 175.00 FL | *- FL |
| 7 | 1 | | *REAR TAILLAMP (LH) | Serviceable | 358.00 FL | *- FL |
| 8 | 1 | | *REAR TAILLAMP LOWER BRACKET (LH) | Serviceable | 95.00 FL | *- FL |
| F=Fra | nchise | part. L=ListIt | emDisc. | | | |
| | | | | Sub Total (S\$) | 2,537.00 | 677.00 |
| | | | - List Item Discount on L Items | 25.00/25.00% (S\$) | 634.25 | 169.25 |
| | | | | Total Parts (S\$) | 1,902.75 | 507.75 |

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|----------|------------|--------|
| Lab | our Items | | | |
| 1 | TO KNOCK REAR END PANEL ,REAR FENDER LH ,WELD & REPLACE ABOVE | New | 700.00 | 200.00 |
| 2 | TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA | New | 700.00 | 200.00 |
| 3 | TO CHECK WIRING | New | 30.00 | 0.00 |
| 4 | TO APPLY ANTI RUST COATING | New | 80.00 | 0.00 |
| | Gross Labour Cost (S\$) | | 1,510.00 | 400.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >