

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20001893/KKA3Q2

Date: 07/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994130

Claimant
Vehicle No : SLW4386Y **Insured Vehicle No :** GBC5698P

Date of Loss: 22/01/2020 Nature of Claim: TP Claim No: 1527492372SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW4386Y		
Make & Model:	MERCEDES-BENZ E200 AVG, 2.0 (R18 LED) (A)	Engine No:	27492031288764
Reg. Date:	12/02/2018 (Man. Year: 2017)	Chassis No:	WDD2130422A366238
Colour:	Metallic Dark Blue	Odometer:	22893 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	615.00	755.00	55.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,370.00	615.00	755.00	55.11
+ GST 7.00/7.00% (S\$)	95.90	43.05	52.85	55.11
Nett Amount (S\$)	1,465.90	658.05	807.85	55.11
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		865.50		
Global Sum Settlement (S\$)		865.00		

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 04/02/2020 Inspected At:

Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPE ,LHR FENDER)	New	600.00	150.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,LHR FENDER)	New	600.00	450.00
3	TO CHECK WIRING	New	50.00	15.00
4	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
Gross Labour Cost (\$\$)			1,370.00	615.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >