

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20001895/KGS3Q2

Date: 08/10/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00003219-02

Claimant
Vehicle No : GBK979U **Insured Vehicle No :** SLB8972P

Date of Loss: 03/02/2020 Nature of Claim: TP Claim No: 1202000004715

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK979U		
Make & Model:	TOYOTA HIACE, 2.8 D (A)	Engine No:	1GD8406192
Reg. Date:	27/12/2019 (Man. Year: 2019)	Chassis No:	GDH2012005767
Colour:	White	Odometer:	4778 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,059.50	5,039.41	15,020.09	74.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	1,000.00	3,960.00	79.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,019.50	6,039.41	18,980.09	75.86
+ GST 7.00/7.00% (S\$)	1,751.37	422.76	1,328.61	75.86
Nett Amount (S\$)	26,770.87	6,462.17	20,308.70	75.86
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
		(S\$) 7,062.17		
Liabe Amount (80.00%) (S\$)		5,649.74		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,657.19		

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 05/02/2020 Inspected At:

CT Auto Pte Ltd (HQ)
160 Sin Ming Drive, #02-14, Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jul 2020)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK979U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	903.70 FL	*825.50 FL
2	1		*BONNET LOCK MECHANISM	Repair	81.50 FL	*- FL
3	1		*BONNET LOCK BRASE PANEL	Repair	110.40 FL	*- FL
4	1		*BONNET CENTRE LOGO	Necessary	150.00 FL	*60.00 FL
5	1		*FRONT GRILLE	Mtg Cracked	1,944.30 FL	*921.52 FL
6	1		*FRONT GRILLE WEATHERSTRIP	Serviceable	342.20 FL	*- FL
7	1		*FRONT SUPPORT PANEL	Repair	819.80 FL	*- FL
8	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	132.80 FL	*- FL
9	1		*FRONT R/H HEAD LAMP LED	Scratched / Cracked	2,484.20 FL	*2,344.45 FL
10	1		*FRONT R/H CORNER PANEL	Repair	294.40 FL	*- FL
11	1		*FRONT WIPER TANK	Serviceable	52.20 FL	*- FL
12	1		*BRAKE BOOSTER	Serviceable	649.60 FL	*- FL
13	1		*BRAKE BOOSTER PUMP	Serviceable	489.10 FL	*- FL
14	1		*BRAKE BOOSTER OIL TANK	Serviceable	151.00 FL	*- FL
15	1		*BRAKE BOOSTER PIPE	Serviceable	225.90 FL	*- FL
16	1		*BRAKE BOOSTER VACUUM PIPE	Serviceable	117.90 FL	*- FL
17	1		*FRONT AIR-CON CONDENSOR	Serviceable	1,095.70 FL	*- FL
18	1		*FRONT AIR CON BLOWER	Serviceable	865.80 FL	*- FL
19	2		*FRONT RADIATOR	Serviceable	2,654.40 FL	*- FL
20	1		*FRONT RADIATOR FAN WITH MOTOR	Serviceable	648.60 FL	*- FL
21	1		*FRONT RADIATOR FAN COWLING	Serviceable	130.70 FL	*- FL
22	2		*FRONT RADIATOR MOUNTINGS	Serviceable	115.80 FL	*- FL
23	1		*FRONT RADIATOR TANK	Serviceable	303.60 FL	*- FL
24	2		*FRONT HORN	Serviceable	257.10 FL	*- FL
25	1		*AIR CLEANER BOX ASSY	Serviceable	582.10 FL	*- FL
26	1		*FRONT INTER COOLER	Serviceable	1,285.10 FL	*- FL
27	1		*FRONT INTER COOLER HOUSING GARNISH	Serviceable	301.20 FL	*- FL
28	1		*FRONT INTER COOLER HOUSING GARNISH WEATHERSTRIP	Serviceable	126.50 FL	*- FL
29	1		*FRONT INTERCOOLER DISCHARGE PIPE	Serviceable	265.60 FL	*- FL
30	1		*FRONT INTERCOOLER SUCTION PIPE	Serviceable	556.70 FL	*- FL
31	1		*FRONT BUMPER INNER L/H RADIATOR	Serviceable	670.60 FL	*- FL
32	1		*FRONT BUMPER	Buckled	649.60 FL	*486.00 FL
33	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	239.90 FL	*119.95 FL
34	1		*FRONT BUMPER LOWER GRILLE	Dented	264.90 FL	*264.90 FL
35	1		*FRONT BUMPER REINFORCEMENT	O/S Cracked	1,239.30 FL	*497.10 FL
36	1		*FRONT BUMPER REINFORCEMENT BRACKET	Repair	148.20 FL	*- FL
37	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
38	1		*SET FRONT GRILLE CLIPS	Necessary	80.00 FS	*80.00 FS
39	1		*FRONT BONNET STICKER	Necessary	250.00 FS	*100.00 FS
40	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
41	1			Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS			
42	1		*SET FRONT HEAD LAMP CLIPS	O/S Necessary	80.00 FS	*40.00 FS
43	2		*FRONT HEAD LAMP SEALANT	Not Necessary	120.00 FS	*- FS
44	1		*BRAKE BOOSTER FLUID	Not Necessary	180.00 FS	*- FS
45	1		*FRONT RADIATOR COOLANT	Not Necessary	160.00 FS	*- FS
46	1		*SET FRONT INTER COOLER HOUSING GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
48	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*SET FRONT NO PLATE	Serviceable	80.00 FS	*- FS
50	1		*FRONT R/H HEAD LAMP WIRE HARNESS	Cracked	196.70 FL	*196.70 FL
51	1		*FRONT L/H HEAD LAMP LED	Serviceable	2,484.20 FL	*- FL
52	1		*FRONT AIR CLEANER BOX	Cracked	780.00 FL	*508.40 FL
53	1		*FRONT AIR DUCT HOLDER	Dented	134.70 FL	*134.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 26,296.00 6,629.22
- List Item Discount on L Items 25.00/25.00% (\$\$) 6,236.50 1,589.81

Total Parts (\$\$) 20,059.50 5,039.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN AND REPLACE FRONT DAMAGED PARTS	New	1,800.00	450.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	1,600.00	500.00
3	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS	New	120.00	0.00
4	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AHD CHECK FOR LEAKAGE	New	120.00	0.00
5	TO REMOVE AND INSTALL INTERCOOLER TO FACILITATE THE REPAIR	New	120.00	0.00
6	TO REMOVE AND INSTALL FRONT DASHBOARD TO FACILITATE THE REPAIR	New	350.00	0.00
7	TO REMOVE AND INSTALL FRONT WINDSCREEN TO FACILITATE THE REPAIR	New	250.00	0.00
8	TO PERFORM 4 WHEEL ALIGNMENT AND BALANCING	New	150.00	0.00
9	TO CHECK WIRING AND FOCUS FRONT HEAD LAMP	New	80.00	20.00
10	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM	New	120.00	0.00
11	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	250.00	30.00
Gross Labour Cost (\$\$)			4,960.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >